





Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 23419190	Plate Category	: PRIVATE
Transaction Date	: 06 JAN 2021 14:31:56	Plate Number	: 056919 EA
Queue Number	: 277227	Import Doc. Ref.	:
Chassis Number	: SJKCH5CPXJA056919	Manufacturer/Model	: INFINITI/QX30
Engine Number	:	Model Year	: 2018
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.06 - Steering Wheel Alignment		ميزانية عجلة القيادة
02.13 - Stub Axle Assemblies, Boots		المحور
		FRONT RIGHT INNER AXLE BOOT GREASE LEAK
03 Brake System		نظام الفرامل
03.01 - Brake Efficiency Front Wheels Left And Right Hands		قوة فرامل المحور الامامي
		BRAKE ROTORS RUSTY
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
		ALL TIRES DOT 2017
04.07 - Rims		الرنجات
		MINOR SCRATCHES
05 Body		الهيكل
05.02 - Paint		الصيغ
		BODY MINOR SCRATCHES & DENTS
06 General Items		الاشياء العامة
06.02 - Wiper Arms		أذرع ماسحات الزجاج
		FRONT WIPER ARMS MALFUNCTION / REAR WIPER BLADE MISSING
06.04 - Horn		الزامور
		MALFUNCTION AIRBAG NOT CHECKED
06.14 - Transmission Condition		حالة ناقل الحركة
		OK
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
		OK
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
		26569 KMS/ HOOD PROP MISSING/ AIR INTAKE DUCT REPAIRED
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.06 - Chassis Ok		الشاصي جيد
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
		FRONT FENDER REFITTED/ BUMPER / BUMPER SUPPORT REFITTED



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 23419190	Plate Category	: PRIVATE
Transaction Date	: 06 JAN 2021 14:31:56	Plate Number	: 056919 EA
Queue Number	: 277227	Import Doc. Ref.	:
Chassis Number	: SJKCH5CPXJA056919	Manufacturer/Model	: INFINITI/QX30
Engine Number	:	Model Year	: 2018
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

09.24 - Digital Display Damaged/Warning Lights	ENGINE MALFUNCTION/ ABS/ TRACTION CONTROL FAULTY/ LOW COOLANT MESSAGES ON	عطل في لوحة التحكم الالكتروني
<p>The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.</p> <p style="text-align: right;">شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط تسجيل غير مسئولة عن العيوب الخفية</p>		

Test Certificate



Vehicle
Registration



✓ PASS

Export Certificate :	64265223
Chassis No :	SJKCH5CPXJA056919
Vehicle Make :	INFINITI
Vehicle Model :	QX30
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) -- x -- x --	
Current Odometer :	26568 Kms.
Origin : Great Britain	Model Year : 2018
Gear Type : --	Engine Size : 5600 CC
Engine No : 270920314...	Horse Power : 208
Axles No : 2	Cylinders : 4
No Of Doors : 4	No Of Seats : 5
G. V. W. : 1900 Kgs.	Empty Weight : 1400 Kgs.

Certificate Number :	5-TAM-2021-13305403
Inspection Date :	04-01-2021
Certificate Print Date :	04-01-2021
Services :	Registration Test
Vehicle Testing Partner :	Tamam
Vehicle Testing Center :	Tamam Vehicles Testing
Total Time Taken :	11 min 52 sec
Appointment Ref Number :	--
Start Time : 12:27	End Time : 12:39
Lane : 02	Token No. : 91
Attempt : 1	Prints No : 1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)

3 KM Distance per year	1 L Fuel consumed per year	2 AED Fuel cost per year	0.1 ton Carbon footprint per year
---------------------------	-------------------------------	-----------------------------	--------------------------------------

Parameter Readings

Service brake imbalance on front axle 15 %	Service brake imbalance on rear axle 9 %	Parking brake imbalance between LHS and RHS 17 %	Vehicle on Petrol CO Reading 0 %
---	---	---	-------------------------------------

Vehicle on Petrol HC Reading
0 PPM VOL

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	5600	2000	
Description - Registration Incorrect Vehicle Description	SALOON	STATION	

Payment Details

Inspection Performed by 59189	Payment Method Cash	Transaction Number 13305403	Service Fees AED 170 Collected on 04/01/2021
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Muralikrishnan P

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

1 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسؤولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995

