





Test Certificate

| | | | |
|---------------------|------------------------|--------------------|----------------|
| Site Number | : 840-EMIRATES AUCTION | Plate Code | : 0 |
| Transaction Number | : 20102373 | Plate Category | : PRIVATE |
| Transaction Date | : 01 JUL 2020 09:47:24 | Plate Number | : 238594 EA |
| Queue Number | : 191150 | Import Doc. Ref. | : |
| Chassis Number | : 1FA6P8CF3H5238594 | Manufacturer/Model | : FORD/MUSTANG |
| Engine Number | : | Model Year | : 2017 |
| Vehicle Class | : LIGHT VEHICLE | Vehicle Color | : BLUE-BLACK |
| Service / Indicator | : DSC AUCTION | | |

Statement of Vehicle Condition

| Defect | Result | Remarks | |
|--|--------|--|-------------------------------|
| AUTOMATIC TEST: | | | |
| 13 Brake System | | | الفرامل |
| 13.04 - Brake Test | Passed | | فحص الفرامل |
| 14 Exhaust Gas Test | | | الغاز العادم والكربون |
| 14.01 - Exhaust Gas Test | Passed | | فحص الغاز العادم-الكربون |
| 16 Side Slip Test | | | فحص ميزانية الاطارات |
| 16.01 - Side Slip Test | Passed | | فحص ميزانية الاطارات |
| VISUAL TEST: | | | |
| 04 Tires Rims | | | الاطارات والعجلات |
| 04.01 - Front Left And Right Hands Tires | | TIRES 2019 | الاطارات الامامية |
| 05 Body | | | الهيكل |
| 05.03 - Doors | | FLEFT DOOR LOCK COVER MISSING | الابواب |
| 05.04 - Fenders | | FRONT LEFT FENDER REPLACED | المدكار |
| 05.05 - Bumpers | | FRONT BUMPER REPLACED & REAR CRACK | الدعامية |
| 05.08 - Chassis (Frame) | | FRONT BOTH SIDE FRAME MEMBER REPAIRED | الشاصية |
| 05.09 - Front And Rear Windshields | | FRONT CRACK | الزجاج الامامي والخلفي |
| 05.12 - Side Safety Frame | | BULKHEAD /& FRONT LEFT FENDER FRAME REPAIRED | الواقيات الجانبية |
| 06 General Items | | | الاشياء العامة |
| 06.13 - Exhaust System | | EXHAUST MODIFIED WITH HEADERS (NOISY) | نظام العادم |
| 07 Remarks | | | ملاحظات |
| 07.04 - Others | | 33087 KM (BONNET REPLACED)MODIFIED | ملاحظات اخرى |
| 09 Auction | | | الفحص الكامل |
| 09.02 - Need Wheel Alignment | | | يحتاج الى ميزانية العجلات |
| 09.09 - Engine And Gear Box Performance Ok | OK | | فحص حالة الماكينة والجير |
| 09.14 - Sign Of Front Accident | | | اثر حادث في مقدمة المركبة |
| 09.15 - Sign Of Rear Accident | | | اثر حادث في مؤخرة المركبة |
| 09.23 - Air Bag Damaged | | LEFT CURTAIN AIR BAG DEPLOYED & CUT | المخدة الهوائية لا تعمل |
| 09.24 - Digital Display Damaged/Warning Lights | | AIR BAG LIGHT ON | عطل في لوحة التحكم الالكتروني |



Test Certificate

| | | | |
|---------------------|------------------------|--------------------|----------------|
| Site Number | : 840-EMIRATES AUCTION | Plate Code | : 0 |
| Transaction Number | : 20102373 | Plate Category | : PRIVATE |
| Transaction Date | : 01 JUL 2020 09:47:24 | Plate Number | : 238594 EA |
| Queue Number | : 191150 | Import Doc. Ref. | : |
| Chassis Number | : 1FA6P8CF3H5238594 | Manufacturer/Model | : FORD/MUSTANG |
| Engine Number | : | Model Year | : 2017 |
| Vehicle Class | : LIGHT VEHICLE | Vehicle Color | : BLUE-BLACK |
| Service / Indicator | : DSC AUCTION | | |

Statement of Vehicle Condition

| | | |
|--|------------------------|--------------------|
| 09.25 - Body Repainted | BODY PORTION REPAINTED | أثر صدى في المركبة |
| <p>The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.</p> | | |

Test Certificate



PASS

| | |
|---------------------------------------|--------------------------|
| Possession Certificate : 64318132 | |
| Chassis No : | 1FA6P8CF3H5238594 |
| Vehicle Make : | FORD |
| Vehicle Model : | MUSTANG |
| Vehicle Class : | Light Vehicle |
| Body Type : | SALOON |
| Fuel : | Benzene |
| Color : | Blue |
| Drive Direction : | -- |
| Dimensions : (H x W x L) -- x -- x -- | |
| Current Odometer : | 33088 Kms. |
| Origin : United States | Model Year : 2017 |
| Gear Type : -- | Engine Size : 6800 CC |
| Engine No : NILL | Horse Power : 435 |
| Axles No : 2 | Cylinders : 8 |
| No Of Doors : 2 | No Of Seats : 4 |
| G. V. W. : 2100 Kgs. | Empty Weight : 1681 Kgs. |

| | |
|-----------------------------|--------------------------|
| Certificate Number : | 5-TAS-2020-12093190 |
| Inspection Date : | 04-07-2020 |
| Certificate Print Date : | 04-07-2020 |
| Services : | Registration Test |
| Vehicle Testing Partner : | Tasjeel |
| Vehicle Testing Center : | Tasjeel Emirates Auction |
| Total Time Taken : | 12 min 21 sec |
| Appointment Ref Number : -- | |
| Start Time : 11:16 | End Time : 11:28 |
| Lane : 01 | Token No. : 2 |
| Attempt : 1 | Prints No : 1 |

Carbon footprint



Keep protecting Dubai environment

Estimated Vehicle Consumption (Rate last 12 Months)

| | | | |
|-------------------------------|----------------------------------|--------------------------------|--------------------------------------|
| | | | |
| 18485 KM Distance per year | 1903 L Fuel consumed per year | 3083 AED Fuel cost per year | 4.6 ton Carbon footprint per year |

Parameter Readings

| | | | |
|--|---|--|--|
| Service brake imbalance on front axle 2 % | Service brake imbalance on rear axle 3 % | Parking brake imbalance between LHS and RHS 3 % | Vehicle on Petrol CO Reading 0.99 % |
|--|---|--|--|

Vehicle on Petrol HC Reading
189 PPM VOL

Inspection Findings

| Discrepancies | Old Value | New Value | Verified |
|--|-----------|--------------|----------|
| Engine Size Discrepancy in Engine Size | 6800 | 5000 | |
| Paint Different color | Blue | Blue , Black | Verified |

Inspection Remarks: FRONT BOTH SIDE SIDE FRAME MEMBER //FRONT BULK HEAD,BOTH SIDE FENDER REPAIRED (OLD)