



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>25 Sep 2022, 10:59:37</b>
Transaction Number	<b>86543297 (CC10006)</b>	Queue Number	<b>593312</b>



Chassis Number	<b>WBAVL510XBVP17274</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>BMW</b>
Model	<b>X1</b>
Model Year	<b>2011</b>
Color	<b>Brown</b>
Mileage	<b>177336 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Sign of front accident		وجود مؤشر لحادث في المقدمة
01.B Other	FRONT BUMPER FRAME ,FENDER FRAME ,BULKHEAD ,CROSS MEMBER ,RADIATOR SUPPORT REPAIRED.	اخرى
01.C Bonnet	REFITTED REPAINTED ,LOCK HANDLE REPAIRED.	غطاء المحرك
01.D Paint	BODY TOTALLY REPAIRED REPAINTED ,EXCEPT ROOF .MINOR DENTS SCRATCHES PORTION FADED. .	الصبغ
<b>02 Lights</b>		<b>الاضاءة</b>
02.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
02.B Tail Light	BOTH SIDE COVER CRACKED.	الانارة
<b>03 Interior Condition</b>		<b>الحالة الداخلية</b>
03.A AC Condition	OK	المكيف
03.B Sun Visor	LEFT SIDE COVER MISSING.	حاجب الشمس
03.C Roof Ceiling	LOOSE	بطانه السقف
<b>04 Tires and Rims Condition</b>		<b>الاطارات</b>
04.A Rear Tyre	LEFT 2018 CRACK, RIGHT 2017 CRACK EXPIRED.	الاطار الخلفي
04.B Front Tyre	RIGHT 2019 WORN OUT & LEFT 2021.	الاطار الامامي

DEFECT	REMARKS	
<b>05 Engine Condition</b>		<b>المحرك</b>
05.A Visual Engine Condition	REFITTED OIL LEAK.	حالة المحرك النظري
<b>06 Transmission Condition</b>		<b>الجير</b>
06.A Visual Gear Box Condition	REFITTED,LEAK.	حالة الجير النظري
06.B Road Test	NOT CHECK	فحص علي الطريق
<b>07 Suspension System</b>		<b>ممتص الصدمات</b>
07.A Shock Absorber	LEAK.	ممتص الصدمات
07.B Arms	LOWER ARM BUSHES CRACK.	ازرع
07.C Ball Joint	BOOT CUT .	مفصل كروي
<b>08 Steering Condition</b>		<b>المقود</b>
08.A Steering Box	OIL LEAK.	جهاز المقود
<b>09 Chassis Condition</b>		<b>الشاسي</b>
09.A Chassis	FRONT LEFT CHASSIS MINOR DENT.	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



X FAILED

Possession Certificate :	66893520
Chassis No :	WBAVL510XBVP17274
Vehicle Make :	BMW
Vehicle Model :	X1
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	Brown
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	177337 Kms.
Origin : Germany	Model Year : 2011
Gear Type : Automatic	Engine Size : 3000 CC
Engine No : 17277587	Horse 218
Axles No : 2	Power :
No Of 4	Cylinders : 6
Doors :	No Of Seats : 5
G. V. W. : 1900 Kgs.	Empty 1400 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17723830		
Inspection Date :	27-09-2022		
Certificate Print Date :	27-09-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	11 min 55 sec		
Appointment Ref Number :	--		
Start Time :	11:42	End Time :	11:54
Lane :	02	Token No. :	9
Attempt :	1	Prints No. :	1

## Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
8 %	5 %	4 %	0 %

Vehicle on Petrol HC Reading  
0 PPM VOL

## Inspection Findings

Defects	Issue	Severity
Tire replace all tires/worn out&dry crack	Cracked	Major

Inspection Remarks: front bumper,bulk head,fender,fender frame,front left frame member end repaired,minor engine oil leak.

## Payment Details

Inspection Performed by 35063	Payment Method VTP Credit Account	Transaction Number 17723830	Service Fees AED 170 Collected on 27/09/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتسجيل الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.