
CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2906109
Transaction Date	29 Oct 2026, 13:23:18
Site Name	840 - Emirates Auctions
Transaction Number	73564548 (CC10010) (CC10011)



Vehicle Details

Chassis Number	**********
Specification	GCC Specification
Make	Nissan
Model	Sunny
Model Year	2002
Color	White
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT REFITTED	مدكار
01.B Paint	BODY REPAIRED REPAINTED MINOR DENT SCRATCHES , PORTION GETTING FADED RUSTY	الصبغ
01.C Doors	FRONT LEFT SIDE NOT OPEN	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.F Bumper	MISALIGN , GRILL PORTION DAMAGED	دعامية
01.G Bonnet	REFTTED	غطاء المحرك
01.H Trunk	REFITTED MISALIGN	صندوق
01.I Sign of side accident	FRONT BUMPER FRAME FENDER FRAME BULKHEAD RADIATOR SUPPORT REPAIRED	وجود مؤشر لحادث في الجانب
01.J Sign of back accident	BACK PANEL QUARTER PANEL COMPARTMENT FLOOR REPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT LEFT SIDE CHASSIS BEND KINK.	الشاسيه
02.B Chassis Number	VIN CORRECTED,JN1FN61C92W013209	رقم القاعدة
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	ENGINE NOT STARTING ALL SYSTEM NOT CHECKED, REFITTED OIL LEAK PARTS RUSTY.OIL STICK DAMAGED	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**

Condition	Remarks	الحالة
04.A Seat Condition	DRIVER SEAT HEADREST MISSING.	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	CRACKED EXPIRED	الاطار الامامي
06.B Rear Tyre	CRACKED EXPIRED	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED , RIGHT SIDE BRACKET REPAIRED,ALL LIGHT NOT CHECK	الاضاءة الرئيسية
07.B Tail Light	FADED MISALIGN , RIGHT SIDE CRACK	الضوء الخلفي
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK	ممتص الصدمات
09.B Arms	BUSHES CUT	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT	ربلة المقود
10.B Steering Box	OIL LEAK	جهاز المقود
11 Interior Condition		الحاله الداخليه
11.A Other	CENTER CONSOLE BOX LOCK COVER DAMAGED / INTERIOR PARTS RUSTY,SIGN OF FLOODED	اخري
11.B Mirror	LEFT SIDE COVER MISSING	المرايا
11.C AC Condition	NOT CHECK	المكيف
11.D Dash Board	WORN OUT , PORTION DAMAGED	لوحة القياده
11.E Door Panel	WORN OUT , PORTION CRACK	لوحة بطانة الباب
11.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae