

TEST CERTIFICATE

Site Number
Transaction Number

840-Emirates Auctions 50903398 (CC10006) Transaction Date

13 Sep 2021, 13:39:15

1HGCV1F15LA026260

Queue Number

Chassis Number

312309



Engine Number

Vehicle Class Car

Manufacturer Honda

Model Accord

Model Year 2020

Color Blue

Mileage 4574

DEFECT	REMARKS	
O1 Body		جسم المركبة
01.A Fenders	RIGHT SIDE BOTH REPAINTED	مدكار
01.B Paint	PORTION REPAIRED , REPAINTED & DENTS ,SCRATCHES ON BODY	الصبغ
01.C Doors	RIGHT SIDE BOTH DOOR REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Pillars	RIGHT SIDE B/ PILLAR REPAIRED	القوائم
01.F Roof	RIGHT SIDE ROOF RAIL REPAINTED	السقف
01.G Other	FOR RECHECK PROPERLY NEED TO REMOVE CENTER PILLAR INNER, ROCKER PANEL COVER	اخري
02 Chassis Condition		الشاصي
02.A Chassis	OK	الشاسيه
03 Seats Condition		المقاعد
03.A Other	OK	اخري
04 Engine Condition		المحرك
04.A Other	OK	اخري
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2019	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2019	الاطار الخلفي

DEFECT	REMARKS	
06 Lights		الاضاءة
06.A Head Light	ОК	الاضاءة الرئيسية
06.B Other	ОК	اخري
07 Transmission Condition		الجير
07.A Gear Box	OK	الجير
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	GETTING RUSTY	ممتص الصدمات
09 Steering Condition		المقود
09.A Axel	GETTING RUSTY	اكسلات
10 Interior Condition		الاجزاء الداخلية
10.A Other	ОК	اخري
10.B Mirror	ОК	المرايا
10.C AC Condition	ОК	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.