CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	3013161
Transaction Date	20 Nov 2026, 14:07:28
Site Name	840 - Emirates Auctions
Transaction Number	30087584 (CC10013) (CC10011)



Vehicle Details

Chassis Number	WDDUG8CB5F*******
Specification	GCC Specification
Make	Mercedes
Model	SL 500
Model Year	2015
Color	White
Mileage	92581 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REAR BOTH SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.C Doors	LEFT SIDE BOTH REPAINTED PORTION REPAIRED & REAR RIGHT PORTION REPAINTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDR FLOOR FULLY COVERED , COVER PORTION CRACK	الارضية
01.F Bumper	MISALIGN PORTION CRACK	دعامية
01.G Windshield	REAR CURTAIN NOT WORKING PROPERLY,MISALIGN	زجاج
01.H Vehicle Model	S500	طراز المركبة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED DIRTY CHECK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		المحرك
03.A Other	DIPSTICK HOLDER DAMAGED	اخري
03.B Engine Visual Condition	REFITTED , ABNORMAL NOISY , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	FRONT BOTH SEAT BACK COVER PORTION LOOSE,LEFT SIDE PORTION CUT WORN OUT	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	JERKING , RFEITTED , PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Propeller Shaft	FLANGE RUBBER DRY CRACK	ناقل الحركة
05.C Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2026	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES	حالة الجنوط
07 Suspension System		ممتص الصدمات
07.A Arms	ARM BUHSES DRY CRACK	ازرع
07.B Other	SUSPENSION PARTS REFITTED	اخري
07.C Ball Joint	BOOT CUT	مفصل كروي
08 Interior Condition		الحاله الداخليه
08.A Other	CENTER CONSOEL BOX COVER PANEL PORTION WORN OUT,CUP HOLDER COVER STUCK , INTERIOR PARTS GETTING RUSTY	اخري
08.B AC Condition	OK	المكيف
08.C Roof Ceiling	PORTION LOOSE	بطانه السقف
08.D Engine Start Button	SMART KEY MISSING	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae