CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2906064
Transaction Date	30 Oct 2026, 14:55:03
Site Name	840 - Emirates Auctions
Transaction Number	50658587 (CC10010) (CC10011)



Vehicle Details

Chassis Number	1N4AL21D68*******
Specification	GCC Specification
Make	Nissan
Model	Altima
Model Year	2008
Color	Silver
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT REFITTED,RIGHT SIDE DAMAGED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,DENTS SCRATCHES,FADED PORTION RUSTY	الصبغ
01.C Doors	DEEP DENTS	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.F Bumper	MISALIGN PORTION DAMAGED	دعامية
01.G Windshield	REAR DAMAGED	زجاج
01.H Bonnet	REFITTED,STAY ROD MISSING	غطاء المحرك
01.I Trunk	NOT OPEN	صندوق
01.J Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
01.K Sign of back accident	BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED.	وجود مؤشر لحادث في الخلف
01.L Vehicle Color	BROWN	لون المركبة
02 Chassis Condition		الشاصي
02.A Chassis	FRONT CHASSIS ,REAR EXTENSION REPAIRED DENT GETTING RUSTY.	الشاسيه
03 Engine Condition		المحرك
03.A Mount	BUSHES CUT .	كرسي

Condition	Remarks	الحالة
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY,PARTS MISSING,	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	EXTRA COVER,REAR LOOSE	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
05.B Road Test	NOT CHECKED.	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2022 CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRACK PUNCTURE	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED ALL LIGHT NOT CHECK,PORTION DAMAGED	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Arms	BUSHES CUT .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT .	ربلة المقود
10.B Steering Box	OIL LEAK .	جهاز المقود
11 Interior Condition		الحاله الداخليه
11.A Other	CENTER CONSOLE BOX PANEL WORN OUT/INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
11.B AC Condition	NOT CHECK,GRILL PORTION DAMAGED	المكيف
11.C Roof Light	PANEL MISSING	أنارة السقف
11.D Dash Board	EXTRA COVER LOOSE,GLOVE BOX DAMAGED	لوحة القياده
11.E Roof Ceiling	PORTION LOOSE	بطانه السقف
11.F Sun Visor	PORTION LOOSE DAMAGED	حاجب الشمس
11.G Odometer reading	NOT CHECK	قراءة عداد المسافات
11.H Door Panel	PORTION DAMAGED WORN OUT	لوحة بطانة الباب
11.I Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.J Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر wecare@carscheck.ae