



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	30 Jun 2022, 14:04:43
Transaction Number	53102590 (CC10008)	Queue Number	312309



Chassis Number	WDDLJ7GB0EA102271
Engine Number	
Vehicle Class	Car
Manufacturer	Mercedes
Model	CLS 63 AMG
Model Year	2014
Color	White
Mileage	93226 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	REPAINTED,PORZION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORZION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
01.C Doors	REPAINTED,PORZION REPAIRED	أبواب
01.D Bonnet	REPAINTED,PORZION REPAIRED	غطاء المحرك
01.E Floor	LEFT SIDE REINFORCEMENT MINOR DENT .BOTH SIDE FENDER CHASSIS AREA TOO OILY , CHECKED VISIBLE AREA	الارضية
01.F Other	FROTN BUMPER FRAME BULKHEAD RADIATOR ASSMEBLY REFITTED	اخرى
01.G Sign of front accident		وجود مؤشر لحادث في المقدمة
02 Interior Condition		الحالة الداخلية
02.A Other	CENTER CONSOLE BOX OPENING HANDLE DAMAGED&CUP SILDING COVER PORTION DAMAGED	اخرى
02.B AC Condition	NOT WORKING	المكيف
02.C Dash Board	LEATHER PORTION LOOSE &REAR WINDSHIELD CURTAIN NOT WORKING	لوحة القيادة
02.D Mirror	LEFT SIDE FOLDING NOT WORKING PROPERLY	المرآيا

DEFECT	REMARKS	
03 Tires and Rims Condition		الاطارات
03.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2020/2021 INNER WORN OUT	الاطار الخلفي
04 Engine Condition		المحرك
04.A Visual Engine Condition	OIL LEAK REFITTED ,UPPER ENGINE COVER MISSING &AIR FILTER &PIPE MODIFIED	حالة المحرك النظري
04.B Mount	MOUNT RUBBER CRACKED	كرسي
04.C Smoke	BLACK SMOKE	دخان
05 Steering Condition		المقود
05.A Axle	LEAK	اكسلات
05.B Tie Rod End	BOOT CUT	مؤخرة الرودادات
06 Suspension System		ممتص الصدمات
06.A Ball Joint	BOOT CUT	مفصل كروي
06.B Arms	LOWER ARM BUSHES CRACKED	ازرع
07 Chassis Condition		الشاسي
07.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
08 Transmission Condition		الجير
08.A Road Test	NOT CHECK	فحص علي الطريق
08.B Visual Gear Box Condition	SIGN OF MINOR OIL LEAK , REFITTED	حالة الجير النظري
09 Seats Condition		المقاعد
09.A Seat Condition	RIGHT SIDE SEAT ADJUSTMENT BUTTON LOOSE	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.