

Queue Number	2836154	Transaction Date	05 Oct 2026, 12:32:31
Site Name	840 - Emirates Auctions	Transaction Number	95927446 (CC10010) (CC10010)



Vehicle Details

Chassis Number	VF1LZL5T8B*****
Specification	GCC Specification
Make	Renault
Model	Fluence
Model Year	2011
Color	White
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
-----------	---------	--------

01 Body	جسم المركبة
01.A Fenders	FRONT & REAR BOTH IDE REPAINTED PORTION REPAIRED. مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED الصبغ
01.C Doors	REAR LEFT SIDE QUARTER GLASS BROKEN .RIGHT SIDE BOTH REPAINTED PORTION REPAIRED. أبواب
01.D Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY صدأ
01.E Floor	PORTION DENT. الارضية
01.F Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED. دعامية
01.G Bonnet	REFITTED . غطاء المحرك
01.H Trunk	NOT OPEN , صندوق
01.I Door Handle & Lock	FRONT BOTH SIDE OUTER HANDLE MISSING ,INNER HANDLE CRACKED. مقابض الأبواب والأقفال
01.J Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD ,FENDER FRAME REPAIRED. وجود مؤشر لحادث في المقدمة
01.K Sign of back accident	BACK PANEL ,QUARTER PANEL ,COMPARTMENT FLOOR REPAIRED,DENT . وجود مؤشر لحادث في الخلف

02 Chassis Condition	الشاسي
02.A Chassis	FRONT BOTH SIDE CHASSIS END REPAIRED DENT GETTING RUSTY. الشاسيه

03 Engine Condition	المحرك
03.A Mount	BUSHES CRACKED . كرسى
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY الحالة النظرية للمحرك

Condition	Remarks	الحالة
04 Seats Condition		المقاعد
04.A Seat Condition	DIRTY PORTION LOOSE.	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2021/2022 EXPIRED CRACKED WORN OUT .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022 EXPIRED CRACKED WORN OUT .	الاطار الخلفي
06.C Rims Condition	MINOR DENTS SCRATCHES .	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUSTY.	دسك و طنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Arms	BUSHES CUT .	أزرع
10 Steering Condition		المقود
10.A Steering Boot	CRACKED .	ربلة المقود
10.B Steering Box	OIL LEAK.	جهاز المقود
11 Interior Condition		الحالة الداخليه
11.A Other	INTERIOR PARTS RUSTY,SIGN OF FLOODED.	اخرى
11.B Mirror	LOOSE FADED COVER CRACKED.	المرايا
11.C AC Condition	NOT CHECKED	المكيف
11.D Roof Light	GLASS HOLDER MISSING.	أنارة السقف
11.E Odometer reading	NOT CHECKED .	قراءة عداد المسافات
11.F Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
11.G Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
11.H Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص

only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae