



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 17 Nov 2022, 13:06:30 |
| Transaction Number | 39799853 (CC10009) | Queue Number | 624418 |



| | |
|------------------|--------------------------|
| Chassis Number | WDCDA5GB3FA462407 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Mercedes |
| Model | ML 400 |
| Model Year | 2015 |
| Color | Brown |
| Mileage | 107033 Km |
| Fuel Type | Petrol |
| No. Of Cylinders | 6 |
| Specification | GCC Specification |

| DEFECT | REMARKS | |
|------------------------------------|---|--------------------------|
| 01 Transmission Condition | | الجير |
| 01.A Road Test | NOT CHECK | فحص علي الطريق |
| 01.B Visual Gear Box Condition | OK | حالة الجير النظرى |
| 02 Interior Condition | | الحاله الداخليه |
| 02.A AC Condition | OK, RIGHT SIDE GRILL PORTION DAMAGED | المكيف |
| 03 Tires and Rims Condition | | الاطارات |
| 03.A Front Tyre | BOTH SIDE 2019 CRACKED, | الاطار الامامي |
| 03.B Rear Tyre | BOTH SIDE 2019 CRACKED, | الاطار الخلفي |
| 04 Body | | جسم المركبة |
| 04.A Floor | UNDER FLOOR FENDER CHASSIS FULLY COVERED CHECKED VISIBLE AREA ONLY | الارضيه |
| 04.B Paint | BODY REPAINTED PORTION REPAIRED & MINOR DENT ,SCRATCHES, | الصبغ |
| 04.C Trunk | REPAIRED REPAINTED | صندوق |
| 04.D Sign of back accident | | وجود مؤشر لحادث في الخلف |
| 05 Chassis Condition | | الشاصي |

| DEFECT | REMARKS | |
|------------------------------|--|---------------------|
| 05.A Chassis | CHASSIS COVERED CHECKED VISIBLE AREA ONLY OK | الشاسيه |
| 06 Suspension System | | ممتص الصدمات |
| 06.A Arms | BUSHES CRACKED | ازرع |
| 07 Engine Condition | | المحرك |
| 07.A Visual Engine Condition | SIGN OF LEAK | حالة المحرك النظري |
| 07.B Mount | RUBBER CRACKED | كرسي |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.