CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2487589
Transaction Date	25 Jun 2026, 15:07:19
Site Name	840 - Emirates Auctions
Transaction Number	54695821 (CC10010) (CC10019)



Vehicle Details

Chassis Number	WDDUG8CB3H*******
Specification	Imported
Make	Mercedes
Model	
Model Year	2017
Color	White
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT LEFT SIDE REPAINTED, PORTION REPAIRED, REFITTED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENTS & SCRATCHES,PORTION FADED,PORTION RUSTY	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR CHASSIS COMPLETE COVERED PORTION DENT MUDDY ,CHECKED ONLY VISIBLE AREA .	الارضية
01.E Bonnet	REPAINTED, PORTION REPAIRED, REFITTED .	غطاء المحرك
01.F Sign of front accident	FRONT BUMPER FRAME , FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT ,CROSS MEMBER REPAIRED	وجود مؤشر لحادث في المقدمة
01.G Vehicle Model	S550	طراز المركبة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETE COVERED ,NOT VISIBLE PROPERLY , SIGN OF ACCIDENT, NEED TO REMOVE FRONT FENDER COVER UNDER COVER FOR INSPECTION .	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START, ALL SYSTEM NOT CHECKED,REFITTED,OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	COVER PORTION CUT	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECKED,REFITTED,OIL LEAK,PARTS RUSTY	الحالة النظريه للجير
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRACKED	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	WEAK,BODY LEVEL VERY LOW.	ممتص الصدمات
09 Steering Condition		المقود
09.A Steering Boot	CRACKED.	ربلة المقود
09.B Steering Box	OIL LEAK	جهاز المقود
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED.	اخري
10.B AC Condition	NOT CHECKED	المكيف
10.C Odometer reading	NOT CHECKED	قراءة عداد المسافات
10.D Door Panel	PORTION LOOSE	لوحة بطانة الباب
10.E Air Bag	OPEN REFITTED .	وسائد هوائية
10.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae