



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	09 Dec 2022, 12:03:38
Transaction Number	46367197 (CC10009)	Queue Number	638588



Chassis Number	SALLDHMR8DA441665
Engine Number	
Vehicle Class	Car
Manufacturer	Land Rover
Model	Defender
Model Year	2013
Color	Grey
Mileage	104963 Km
Fuel Type	Diesel
No. Of Cylinders	4
Specification	Imported

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED MINOR DNETS SCRATCHES , PORTION FADED	الصبغ
02 Transmission Condition		الجير
02.A DIFFERENTIAL	OIL LEAK ,REAR ARM BUSHES CUT	الدفرنشيل
02.B Road Test	NOT CHECK	فحص علي الطريق
02.C Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
02.D Visual Gear Box Condition	OIL LEAK REFITTED	حالة الجير النظري
03 Interior Condition		الحاله الداخليه
03.A AC Condition	OK	المكيف
04 Tires and Rims Condition		الاطارات
04.A Rear Tyre	BOTH SIDE 2020,	الاطار الخلفي
04.B Front Tyre	BOTH SIDE 2020,	الاطار الامامي
05 Suspension System		ممتص الصدمات
05.A Arms	CONTROL ARM BUSHES CUT	ازرع

DEFECT	REMARKS	
05.B Ball Joint	BOOT CUT	مفصل كروي
06 Steering Condition		المقود
06.A Steering Oil	,MINOR OIL LEAK	زيت المقود
06.B Tie Rod End	BOOT CUT	مؤخرة الرودادات
07 Chassis Condition		الشاسيه
07.A Chassis	BOTH SIDE MIDDLE CHASSIS LOWER DENT, FRONT BOTH SIDE INNER SIDE MINOR DENT/ FRAME THICK RUST PROOFED	الشاسيه
07.B Chassis Number	MANUFACTUR STICKER & WINDSHIRIELD NUMBER MISSING, VIN CHECKED ONLY ON FRAME	رقم القاعدة
08 Engine Condition		المحرك
08.A Mount	MOUNT RUBBER CRACKED	كرسي
08.B Visual Engine Condition	OIL LEAK REFITTED	حالة المحرك النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Export Certificate :	57488215
Chassis No :	SALLDHMR8DA441665
Vehicle Make :	LAND ROVER.
Vehicle Model :	DEFENDER110
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Diesel
Color :	Gray
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	104963 Kms.
Origin : Great Britain	Model Year : 2013
Gear Type : Manual	Engine Size : 3000 CC
Engine No : 13071508165...	Horse 182
Axles No : 2	Power :
No Of 4	Cylinders : 4
Doors :	No Of Seats : 5
G. V. W. : 2500 Kgs.	Empty 1630 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-18282380		
Inspection Date :	10-12-2022		
Certificate Print Date :	10-12-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	16 min 43 sec		
Appointment Ref Number :	--		
Start Time :	14:13	End Time :	14:30
Lane :	03	Token No. :	186
Attempt :	1	Prints No. :	1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)

8746 KM	696 L	2569 AED	1.7 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Turbo K-Value
25 %	26 %	26 %	0.3 PPM VOL

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Vehicle Make - Registration Incorrect Make - Does Not Require Document	LAND ROVER.	LAND ROVER	
Engine Size Discrepancy in Engine Size	3000	2000	
Vehicle Model - Registration Incorrect Model - Does Not Require Document	DEFENDER110	DEFENDER	

Inspection Remarks:

MINOR ENGINE OIL LEAK // CHASSIS HARDLY RUST PROOFED , & CHASSIS MINOR RUSTY //FRONT BUMPER , STEERING WHEEL MODIFIED

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
30544 2151 2151	Cash	18282380	AED 170 Collected on 10/12/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتريخيص الفني للمركبة. لا يمتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية تريخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

