



Test Certificate

Site Number	: 756-TASJEEL SHARJAH	Plate Code	:
Transaction Number	: 18934783	Plate Category	:
Transaction Date	: 07 JAN 2020 09:46:40	Plate Number	:
Queue Number	: 131647	Import Doc. Ref.	: 47173 DXB
Chassis Number	: KMHTC61C5GU247173	Manufacturer/Model	: HYUNDAI/VELOSTER
Engine Number	:	Model Year	: 2016
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: SILVER
Service / Indicator	: DSC AUCTION	Mileage	: 70039

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
17 Shock Absorbers Test		فحص مخمد الصدمات
17.01 - Shock Absorber Test	Passed	فحص مخمد الصدمات
VISUAL TEST:		
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
06 General Items		الاشياء العامة
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
09 Auction		الفحص الكامل
09.06 - Chassis Ok	OK	الشاسي جيد
09.09 - Engine And Gear Box Performance Ok	OK	فحص حالة الماكينة والجير
09.25 - Body Repainted		أثر صيغ في المركبة
		FRONT RHS FENDER,RR B/S Q/PANELS,LS DOOR PORTIONS REPAINTED.
The Test Certificate Shows the test Result at the time of inspection only.		
شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط		