

Queue Number	2827639	Transaction Date	07 Oct 2026, 14:14:42
Site Name	840 - Emirates Auctions	Transaction Number	36107155 (CC10010) (CC10010)



Vehicle Details

Chassis Number	MNTBB7A91G*****
Specification	GCC Specification
Make	Nissan
Model	Sentra
Model Year	2016
Color	White
Mileage	347011 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT & REAR REPAIRED REPAINTED.	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION FADED PORTON RUSTY	الصبغ
01.C Doors	PORTION REPAIRED ,REPAINTED.	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR MUDDY, PORTION DENTS/BOTH SIDE RUNNING BOARD DENT .	الارضية
01.F Bumper	MISALIGN,PORTION DAMAGED . SCRATCHES .	دعامية
01.G Bonnet	REPAIRED REPAINTED .	غطاء المحرك
01.H Sign of front accident	FRONT BUMPER FRAME , FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة
01.I Sign of side accident	LEFT SIDE QUARTR PANEL DAMAGED.	وجود مؤشر لحادث في الجانب
01.J Sign of back accident	BACK PANEL DENT .	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS COMPLETE MUDDY OILY PORTION DENT . PORTION COVERED ,	الشاسيه
02.B Other	STEM WASH CHASSIS FOR INSPECTION .	اخرى
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START, ALL SYSTEM NOT CHECKED,REFITTED,OIL LEAK,PARTS RUSTY	الحالة النظرية للمحرك
04 Transmission Condition		الجير

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	NOT CHECKED,REFITTED,OIL LEAK,PARTS RUSTY	الحالة النظرية للجير
04.B Road Test	NOT CHECKED.	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	EXPIRED CRACKED WORN OUT .	الاطار الامامي
05.B Rear Tyre	EXPIRED CRACKED WORN OUT .	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
06.B Tail Light	PORTION DAMAGED.	الضوء الخلفي
07 Suspension System		ممتص الصدمات
07.A Shock Absorber	LEAK ,TOP MOUNT CUT .	ممتص الصدمات
07.B Arms	BUSHES CUT.	ازرع
08 Steering Condition		المقود
08.A Steering Boot	CUT .	ربلة المقود
08.B Steering Box	OIL LEAK .	جهاز المقود
09 Interior Condition		الحالة الداخلية
09.A Other	UNDER SEATS ,INTERIOR METAL PARTS RUSTY, WATER FLOODED	اخرى
09.B AC Condition	NOT CHECKED. .	المكيف
09.C Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
09.D Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
09.E Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص. ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae