



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **25 May 2023, 11:16:40**  
 Transaction Number **43102370 (CC10010)** Queue Number **720402**



Chassis Number **JTDKW9D39ED549454**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **Toyota**  
 Model **Yaris**  
 Model Year **2014**  
 Color **Silver**  
 Mileage **001 Km**  
 Fuel Type **Petrol**  
 No. Of Cylinders **4**  
 Specification **GCC Specification**

DEFECT	REMARKS	
<b>01 Tires and Rims Condition</b>		<b>الاطارات</b>
01.A Front Tyre	BOTH SIDE 2019 CRACKED .	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2019 CRACKED .	الاطار الخلفي
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Rusty	UNDER BODY ,SUSPENSION PARTS GETTING RUSTY	صدأ
02.B Other	FRONT BUMPER FRAME ,BULKHEAD REPAIRED.	اخرى
02.C Fenders	REFITTED.	مدكار
02.D Roof	RAIL STRIP MISSING.	السقف
02.E Floor	PORTION DENT .	الارضية
02.F Paint	BODY PORTION REPAINTED, PORTION REPAIRED, PORTION FADED ,PORTION RUSTY., DENTS, SCRATCHES ON BODY	الصبغ
02.G Paint	BODY PORTION REPAINTED, PORTION REPAIRED, PORTION FADED ., DENTS, SCRATCHES ON BODY	الصبغ
02.H Bumper	MISALIGN ,PORTION DAMAGE .	دعامية
02.I Sign of front accident		وجود مؤشر لحادث في المقدمة
<b>03 Suspension System</b>		<b>ممتص الصدمات</b>
03.A Arms	LOWER ARM BUSHES CRACKED.	ازرع

DEFECT	REMARKS	
03.B Shock Absorber	LEAK ,WEAK .	ممتص الصدمات
<b>04 Transmission Condition</b>		<b>الجير</b>
04.A Visual Gear Box Condition	NOT CHCKED ,OIL LEAK .	حالة الجير النظري
04.B Road Test	NOT CHECKED .	فحص علي الطريق
<b>05 Interior Condition</b>		<b>الحالة الداخلية</b>
05.A Odometer reading	NOT CHECKED .	قراءة عداد المسافات
05.B AC Condition	NOT CHECKED .	المكيف
05.C Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
<b>06 Lights</b>		<b>الاضاءة</b>
06.A Head Light	LENS FADED ,ALL LIGHTS NOT CHECKED .	الاضاءة الرئيسية
<b>07 Engine Condition</b>		<b>المحرك</b>
07.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING ,,OIL LEAK.	حالة المحرك النظري
<b>08 Chassis Condition</b>		<b>الشاسي</b>
08.A Chassis	CHECKED ONLY VISIBLE AREA OK.	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.