



Test Certificate

Site Number	: 756-SHJ AUTO VILLAGE	Plate Code	:
Transaction Number	: 19876501	Plate Category	:
Transaction Date	: 01 JUN 2020 10:17:21	Plate Number	:
Queue Number	: 181088	Import Doc. Ref.	: 01390 EA
Chassis Number	: 5KBRL5861GB701390	Manufacturer/Model	: HONDA/ODYSSEY
Engine Number	:	Model Year	: 2016
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLACK
Service / Indicator	: DSC AUCTION	Mileage	: 205864

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
17 Shock Absorbers Test		فحص مخمد الصدمات
17.01 - Shock Absorber Test	Failed	فحص مخمد الصدمات
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.11 - Shock Absorbers		مخمد الصدمات
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
05 Body		الهيكل
05.04 - Fenders		المدكار
05.05 - Bumpers		الدعامية
09 Auction		الفحص الكامل
09.01 - Steering Oil Leaking		تهريب زيت صندوق عجلة القيادة
09.06 - Chassis Ok		الشاصي جيد
09.09 - Engine And Gear Box Performance Ok		فحص حالة الماكينة والجير
09.10 - Engine Oil Leaking		تهريب زيت المحرك
09.25 - Body Repainted		أثر صغ في المركبة
The Test Certificate Shows the test Result at the time of inspection only.		
شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط		