



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	18 May 2022, 17:50:10
Transaction Number	64250191 (CC10008)	Queue Number	312309



Chassis Number	JTB11UJAOW9006012
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Land Cruiser
Model Year	1998
Color	White
Mileage	357470 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	RIGHT SIDE BOTH PORTION REPAIRED,REPAINTED	مدكار
01.B Paint	BODY PORTION REPAIRED, REPAINTED,MINOR DENT,SCRATCHES	الصبغ
01.C Floor	UNDER FLOOR MUDDY	الارضية
01.D Doors	REAR RIGHT SIDE PORTION REPAIRED,REPAINTED	أبواب
01.E Bonnet	PORTION REPAIRED,REPAINTED	غطاء المحرك
01.F Other	FRONT BUMPER FRAME RIGHT SIDE FENDER FRAME REPAIRED	اخرى
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الخلفي
03 Suspension System		ممتص الصدمات
03.A Shock Absorber	MODIFIED	ممتص الصدمات
03.B Arms	BOTH SIDE LOWER ARM BUSHES CRACKED	ازرع
03.C Ball Joint	BOOT CUT	مفصل كروي
03.D Other	STABILIZER LINK BOOT CUT	اخرى

DEFECT	REMARKS	
04 Engine Condition		المحرك
04.A Visual Engine Condition	OIL LEAK REFITTED & SHAKING	حالة المحرك النظري
04.B Mount	MOUNT RUBBER CRACKED	كرسي
05 Transmission Condition		الجير
05.A Visual Gear Box Condition	OIL LEAK REFITTED	حالة الجير النظري
05.B Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
05.C Road Test	NOT CHECK	فحص علي الطريق
06 Steering Condition		المقود
06.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
06.B Steering Oil	MINOR OIL LEAK	زيت المقود
06.C Steering Boot	RIGHT SIDE BOOT CUT	ربلة المقود
06.D Axel	BOOT CUT	اكسلات
07 Interior Condition		الحاله الداخليه
07.A AC Condition	REAR LOW COOLING	المكيف
07.B Roof Light	LOOSE	أنارة السقف
08 Seats Condition		المقاعد
08.A Seat Condition	SEATS HAVE EXTRA COVER	حالة المقاعد
09 Chassis Condition		الشاصي
09.A Chassis	OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.