



# Test Certificate

Plate Code

Site Number 840-EMIRATES AUCTION

Transaction Number 24255415

: 0 Plate Category Transaction Date **PRIVATE** 15 FEB 2021 10:59:26 Plate Number Queue Number 900546 EA

297725

Import Doc. Ref. Chassis Number 19XFB2645EE900546 Manufacturer/Model Engine Number : HONDA/CIVIC

Model Year Vehicle Class : 2014 LIGHT VEHICLE Vehicle Color Service / Indicator : GREY

DSC AUCTION

| Defect  | Result  | Remarks   | ment of Vehicle Condition  |
|---|---------|---|--|
| AUTOMATIC TEST:   | rtesuit | Remarks   |  |
| 14 Exhaust Gas Test   |         |   |  |
| 14.01 - Exhaust Gas Test  | Passed  |   | ز العادم والكربون  |
| VISUAL TEST:  | rasseq  |   | س المغاز العادم-الكربون  |
| 03 Brake System   |         |   |  |
| 03.01 - Brake Efficiency Front Wheels Left And<br>Right Hands                                     |         | BRAKE ROTORS RUSTY/ BRAKE PADS  | م الفر امل   |
| 04 Tires Rims   |         | WORN OUT  | فرامل المحور الامامي   |
| 04.01 - Front Left And Right Hands Tires  |         |   | لمارات والعجلات  |
|   |         | FRONT TIRES DOT 2019 & 2016/ REAR<br>TIRES DOT 2017/ FRONT RIGHT TIRE DOT<br>TAMPERED           | لحارات الامامية  |
| 04.07 - Rims  |         | SCRATCHES   |  |
| 05 Body   |         |   | نجات   |
| 05.02 - Paint   |         | PODV CODATOURS A  | پکل  |
| 05.05 - Bumpers   |         | BODY SCRATCHES & DENTS  | سبغ  |
| 05.08 - Chassis (Frame)   |         | REFITTED/ MISALIGN  | عامية  |
| 05.09 - Front And Rear Windshields  |         | FRONT BOTH SIDE MEMBERS REPAIRED  | باصية  |
| 06 General Items  |         | FRONT WINDSHIELD REPLACED   | حاج الامامي والخلفي  |
|   |         |   | تشياء العامة   |
| <ul><li>06.12 - Seats Condition And Seats Fixing</li><li>06.14 - Transmission Condition</li></ul> |         | INTERIOR PARTLY WORN OUT  | قاعد وحالتها وتثبيتها  |
| 06.16 - Engine Condition, Smoke   |         | ОК  | الة ناقل الحركة  |
| 7 Remarks   |         | ОК  | الة المحرك - الدخان  |
|   |         |   | وي السرام و المحالة ال |
| 07.04 - Others  |         | 85583 KMS   |  |
| 9 Auction   |         |   | لاحظات اخرى  |
| 09.02 - Need Wheel Alignment  |         |   | لفحص الكامل  |
| 09.14 - Sign Of Front Accident  |         | FENDER ERAMES/ BUILDINGS  | حاجة الى ميز انية العجلات  |
| 09.15 Sign Of Decree  |         | FENDER FRAMES/ BULKHEAD/ RADIATOR<br>SUPPORT REPAIRED/ FENDERS REPAIRED/<br>HOOD REFITTED       | ثر حادث في مقدمة المركبة   |
| 09.15 - Sign Of Rear Accident   |         | CRASH BRACKET DENT  | أثر حادث في مؤخرة المركبة  |
| 09.16 - Sign Of Side Accident   |         |   |  |
| 09.24 - Digital Display Damaged/Warning Lights  |         | P.STEERING/ ENG M/F/ SRS AIRBAG/ ABS/<br>BRAKE FAULTY/ TPMS/ VSC & OTHER<br>WARNING MESSAGES ON | أثر حادث في جوانب المركبة<br>عطل في لوحة التحكم الالكتروني   |





# Test Certificate

Site Number 840-EMIRATES AUCTION Plate Code Transaction Number

0 24255415

Plate Category Transaction Date **PRIVATE** 15 FEB 2021 10:59:26 Plate Number Queue Number 900546 EA

297725 Import Doc. Ref. Chassis Number

19XFB2645EE900546 Manufacturer/Model Engine Number HONDA/CIVIC

Model Year Vehicle Class 2014 LIGHT VEHICLE Vehicle Color **GREY** 

Service / Indicator **DSC AUCTION** 

Statement of Vehicle Condition

09.25 - Body Repainted BODY PORTIONS REPAINTED ثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.

> شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط تسجيل غير مسنولة عن العيوب الخفية

## **Test Certificate**

PASS









Possession Certificate: 65074692

19XFB2645EE900546 Chassis No: Vehicle Make: HONDA Vehicle Model: CIVIC Vehicle Class: Light Vehicle **Body Type:** SALOON

Fuel: Benzene Color: Brown **Drive Direction:** 

Dimensions: (H x W x L) --x--x--**Current Odometer:** 85585 Kms.

Origin: United States

Gear Type: Engine No: R18Z136514... Axles No:

No Of Doors: 4 G. V. W.: 1850 Kas.

Model Year: 2014

**Engine Size:** Horse Power: Cylinders: No Of Seats:

1800 CC

Empty Weight: 1100 Kgs.

Certificate Number: 5-TAS-2021-13630490

Inspection Date: 18-02-2021 Certificate Print Date : 18-02-2021 Services: Registration Test

Vehicle Testing Partner: Tasjeel

Vehicle Testing Center: Tasjeel Emirates Auction

Total Time Taken: 11 min 9 sec

Appointment Ref Number : --

Start Time: 15:39 Lane: Attempt: 1

End Time: 15:51 Token No.: 11 Prints No: 1

#### Carbon footprint



Thank you! You are environment protector

#### Estimated Vehicle Consumption (Rate last 12 Months)



year

Parking brake imbalance

13412 KM 9531 Distance per Fuel consumed

per year

1544 AED Fuel cost per 2.3 ton

vear

## Carbon footprint per year

#### **Parameter Readings**

Service brake imbalance on front axle

2%

Service brake imbalance on rear axle 6%

between LHS and RHS

Vehicle on Petrol CO Reading

0%

### Vehicle on Petrol HC Reading

26 PPM VOL

### **Inspection Remarks:**

FRONT BOTH SIDE FENDER, WHEEL ARCH, RADIATOR FRAME REPAIRED//UNDER BODY RUST PROOFED// FRONT BOTH SIDE CHASSIS REPAIRED. CCM CHECKED OK: WO NO: 20201011-001

## **Payment Details**

Inspection Performed by **Payment Method Transaction Number** Service Fees 74791 VTP Credit Account 13630490 AED 170 Collected on 18/02/2021 **Parking Slot No Attempt** Received by Service Name **Registration Test** Raul Canceran Galang

- 10 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations. 👖 هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص . المؤسسة غير مسئولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا

لقانون السير و المرور أ2 لسنة 1995 This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995