CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2942517
Transaction Date	04 Nov 2026, 17:49:37
Site Name	840 - Emirates Auctions
Transaction Number	37495156 (CC10009) (CC10011)



Vehicle Details

Chassis Number	1LNHM82V06*******
Specification	Imported
Make	Lincoln
Model	Town
Model Year	2006
Color	Gold
Mileage	188684 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION FADED	الصبغ
01.C Rusty	UNDER BODY PARTS CHASSIS SUSPENSION GETTING RUSTY	صدأ
01.D Floor	FLOOR MUDDY OILY , RUNNING BOARD DENT	الارضية
01.E Bumper	MISALIGN SCRATCHES,CHROME STRIP PORTION CRACKED	دعامية
01.F Windshield	DAMAGED	زجاج
01.G Bonnet	REFITTED,LOGO GETTING FADED	غطاء المحرك
01.H Trunk	LOGO DAMAGED,NUMBER PLATE LIGHT DAMAGED,COMPARTMENT COVER PORTION LOOSE	صندوق
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS PORTION DENT ,GETTING RUSTY PORTION RUST PROOFED	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK REFITTED GETTINTG RUSTY SHAKING	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	COVER PORTION CRACKED WORN OUT,FRONT RIGHT SIDE ADJUSTMENT NOT WORKING PROPERLY	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	OIL LEAK REFITTED GETTING RUSTY JERKING	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACKED	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES,WHEEL HUB OUTER COVER MISSING	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	SWITCH PANEL DAMAGED	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHTS ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Arms	LOWER ARM BUSHES CUT	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
09 Steering Condition		المقود
09.A Steering Oil	OIL LEAK	زيت المقود
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX COVER CRACKED WORN OUT/INNER PARTS GETTING RUSTY,SIGN OF FLOODED	اخري
10.B Mirror	LEFT SIDE LOOSE MISALIGN	المرايا
10.C AC Condition	OK,GRILL PORTION DAMAGED	المكيف
10.D Power Window Switch And Glass	MAIN SWITCH PANEL LOOSE FIX BY GLUE	مفتاح النافذه و الزجاج
10.E Dash Board	PORTION CRACKED DAMAGED	لوحة القياده
10.F Sun Visor	LEFT SIDE MIRROR DAMAGED PART MISSING	حاجب الشمس
10.G Door Panel	PORTION DAMAGED WORN OUT	لوحة بطانة الباب
10.H Steering Wheel and control buttons	WORN OUT,ASSEMBLY COVER PORTION MELTED	عجلة القيادة وازرار التحكم
10.I Gear Shifting Lever	KNOB WORN OUT,DUST COVER DAMAGED	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae