CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2916210
Transaction Date	28 Oct 2026, 14:59:57
Site Name	840 - Emirates Auctions
Transaction Number	54267792 (CC10013) (CC10019)



Vehicle Details

Chassis Number	3GCND9ED1P*******
Specification	GCC Specification
Make	Chevrolet
Model	Silverado
Model Year	2023
Color	Red
Mileage	102001 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY,MINOR DENTS SCRATCHES	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR BODY MOUNT SIGN OF REFITTED	الارضية
01.E Bumper	MISALIGN,PORTION SCRATCHES	دعامية
01.F Trunk	TAIL GATE SWITCH WORN OUT	صندوق
01.G Vehicle Color	MAROON	لون المركبة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FRAME RUST PROOFED , MUDDY , GETTING RUSTY	الشاسيه
02.B Chassis Number	VIN RUST PROOFED , CHECK DOOR POST STICKER	رقم القاعدة
03 Engine Condition		المحرك
03.A Other	ENGINE PARTS & INTAKE PIPE MODIFIED WITH FILTER	اخري
03.B Engine Visual Condition	OPEN REFITTED , OIL WET , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Exhaust System		نظام العادم
04.A Modification	EXHAUST SYSTEM MODIFIED NOISY	تعديلات
04.B Catalytic Converter	MISSING	دبة البيئة

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED , OIL PAN DENT , PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06.D Spare Tire &Tools	MISSING	الاطار الاحتياطي و العدة
07 Suspension System		ممتص الصدمات
07.A Leaf Spring	MISALIGN , BUSHES DRY CRACK	
07.B Other	SUSPENSION PARTS REFITTED	اخري
08 Interior Condition		الحاله الداخليه
08.A Other	INTERIOR PARTS GETTING RUSTY	اخري
08.B Mirror	CENTER MIRROR PORTION LOOSE	المرايا
08.C AC Condition	OK	المكيف

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae