

Queue Number 2788252

Transaction Date 23 Sep 2026, 16:03:27

Site Name
840 - Emirates AuctionsTransaction Number
90284944 (CC10021) (CC10021)

Vehicle Details

Chassis Number WDBWK54F39*****
 Specification GCC Specification
 Make Mercedes
 Model SLK280
 Model Year 2009
 Color Red
 Mileage N/A NA
 Fuel Type Petrol
 Transmission Type
 No. Of Cylinders 6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body	جسم المركبة
---------	-------------

01.A Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION FADED , PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS, SUSPENTION GETTING RUSTY	صدأ
01.C Floor	FLOOR MUDDY,PORTION DENT	الارضية
01.D Bumper	MISALIGN,PORTION DAMAGED .	دعامية
01.E Bonnet	GRILL MISSING	غطاء المحرك

02 Chassis Condition	الشاسيه
----------------------	---------

02.A Chassis	CHASSIS COVERED,CHECKED VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition	المحرك
---------------------	--------

03.A Engine Visual Condition	ENGINE NOT START, ALL SYSTEM NOT CHECKED,REFITTED,OIL LEAK,PARTS RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition	المقاعد
--------------------	---------

04.A Seat Condition	WORN OUT	حالة المقاعد
---------------------	----------	--------------

05 Transmission Condition	الجير
---------------------------	-------

05.A Gear Box Visual Condition	NOT CHECKED,REFITTED,OIL LEAK,PARTS RUSTY	الحالة النظرية للجير
--------------------------------	---	----------------------

05.B Road Test	NOT CHECKED	فحص علي الطريق
----------------	-------------	----------------

06 Tires and Rims Condition	الاطارات
-----------------------------	----------

Condition	Remarks	الحالة
06.A Front Tyre	BOTH SIDE CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACK	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي
09.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY,SIGN OF FLOODED	اخرى
10.B AC Condition	NOT CHECK	المكيف
10.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.D Gear Shifting Lever	WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae