



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	18 Jan 2023, 12:55:59
Transaction Number	16051813 (CC10006)	Queue Number	657698



Chassis Number	1N4AL21E99C160803
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Altima 2.5 SL
Model Year	2009
Color	White
Mileage	001 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	Imported

DEFECT	REMARKS	
01 Transmission Condition		الجير
01.A Visual Gear Box Condition	NOT CHECK,OIL LEAK REFITTED	حالة الجير النظرى
01.B Road Test	NOT CHECK	فحص علي الطريق
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الخلفي
03 Body		جسم المركبة
03.A Other	REAR BACK PANEL ,QUATER PANEL,SPARE WHEEL HOUSING REPAIRED	اخرى
03.B Fenders	FRONT REFITTED	مدكار
03.C Rusty	UNDER BODY PARTS SUSPENSION FLOORING GETTING RUSTY	صدأ
03.D Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,PORTION FADED,PORTION RUSTY	الصبغ
03.E Bumper	MISALIGN,LOGO MISSING	دعامية
03.F Bonnet	REFITTED	غطاء المحرك
03.G Floor	PORTION DENT	الارضية

DEFECT	REMARKS	
03.H Sign of back accident		وجود مؤشر لحادث في الخلف
04 Interior Condition		الحالة الداخليه
04.A Dash Board	PORTION CRACKED	لوحة القيادة
04.B Odometer reading	NOT CHECK	قراءة عداد المسافات
04.C AC Condition	NOT CHECK	المكيف
05 Suspension System		ممتص الصدمات
05.A Other	STABILIZER LINK BOOT CUT	اخرى
05.B Arms	LOWER ARM BUSH CRACKED	ازرع
05.C Ball Joint	BOOT CUT	مفصل كروي
05.D Shock Absorber	LEAK	ممتص الصدمات
06 Steering Condition		المقود
06.A Steering Boot	BOOT CUT	ربلة المقود
06.B Tie Rod End	BOOT CUT	مؤخرة الرودادات
06.C Axle	BOOT CUT	اكسلات
06.D Steering Oil	OIL LEAK	زيت المقود
07 Engine Condition		المحرك
07.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK,KEY MISSING,OIL LEAK REFITTED	حالة المحرك النظري
08 Chassis Condition		الشاصي
08.A Chassis	REAR BOTH SIDE CHASSIS & CHASSIS EXTENSION REPAIRED	الشاسيه
09 Seats Condition		المقاعد
09.A Seat Condition	PORTION DAMAGED	حالة المقاعد
10 Lights		الاضاءة
10.A Head Light	LENS FADED,ALL LIGHT NOT CHECK	الاضاءة الرئيسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.