CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2941875
Transaction Date	04 Nov 2026, 14:28:40
Site Name	840 - Emirates Auctions
Transaction Number	18723195 (CC10008) (CC10008)



Vehicle Details

Chassis Number	MR2K19F32L*******
Specification	GCC Specification
Make	Toyota
Model	Yaris
Model Year	2020
Color	White
Mileage	134656 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE REPAINTED REFITTED ,RIGHT SIDE DENT ,REAR RIGHT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED ,DENT,SCRATCHES	الصبغ
01.C Doors	RIGHT SIDE BOTH DOOR REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Bumper	MISALIGN	دعامية
01.F Roof	REPAINTED PORTION REPAIRED	السقف
01.G Bonnet	REPAINTED PORTION REPAIRED ,REFITTED	غطاء المحرك
01.H Trunk	REPAINTED PORTION REPAIRED	صندوق
01.I Sign of front accident	BULK HEAD ,RADIATOR SUPPORT REPIRED	وجود مؤشر لحادث في المقدمة
01.J Sign of side accident		وجود مؤشر لحادث في الجانب
01.K Sign of back accident	BACK PANEL REPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		**الشاصي**
02.A Chassis Extension	REAR BOTH SIDE CHASSIS EXTENSION END REPAIRED DENT	تمديدات الشاسي
02.B Chassis	FRONT RIGHT SIDE CHASSIS REPAIRED	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	OIL LEAK ,PARTS GETTING RUSTY	الحالة النظريه للمحرك

Condition	Remarks	الحالة
04 Seats Condition		المقاعد
04.A Seat Condition	EXTRA COVER	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	PARTS GETTING RUSY	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025 CRACK	الاطار الخلفي
07 Lights		الاضاءة
07.A Tail Light	RIGHT SIDE DAMAGED	الضوء الخلفي
07.B Warning Light	AIR BAG WARNING LIGHT SHOW IN DISPLAY	ضوء تحذير
08 Brake Condition		الفرامل
08.A Disc&Drum	GETTING RUSTY	دسك وطنابير الفرامل
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED,INTERIOR DIRTY	اخري
09.B AC Condition	OK	المكيف

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae