




## TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	11 May 2022, 12:41:20
Transaction Number	22530430 (CC10006)	Queue Number	312309



Chassis Number	WDD2211711A022023
Engine Number	
Vehicle Class	Car
Manufacturer	Mercedes
Model	S 500
Model Year	2006
Color	White
Mileage	203084 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Paint	BODY PORTION REPAINTED,MINOR DENT,SCRATCHES,	الصبغ
01.B Floor	UNDER BODY FULLY COVERED	الارضية
01.C Bonnet	REPAINTED & REFITTED	غطاء المحرك
<b>02 Interior Condition</b>		<b>الحالة الداخليه</b>
02.A Dash Board	DASH BOARD WORN OUT & CONSOLE BOX BOTTON LOCK DAMAGED	لوحة القيادة
02.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
02.C Sun Visor	RIGHT SIDE COVER MIRROR MISSING	حاجب الشمس
02.D Other	REAR LEFT SIDE SIGRATE BOX COVER DAMAGED	اخرى
02.E AC Condition	OK	المكيف
02.F Sunroof	NOT WORKING	فتحت سقف
02.G Power Window Switch	REAR RIGHT SIDE NOT WORKNG	مفتاح النافذه
<b>03 Tires and Rims Condition</b>		<b>الاطارات</b>
03.A Spare Tire &Tools	MISSING	الاطار الاحتياطي و العدة
03.B Front Tyre	BOTH SIDE 2018 WORN OUT , CRACKED	الاطار الامامي

DEFECT	REMARKS	
03.C Rear Tyre	BOTH SIDE 2018 WORN OUT , CRACKED	الاطار الخلفي
<b>04 Engine Condition</b>		<b>المحرك</b>
04.A Visual Engine Condition	OIL WET	حالة المحرك النظرى
<b>05 Transmission Condition</b>		<b>الجير</b>
05.A Propeller Shaft	RUBBER CRACKED	ناقل الحركة
05.B Road Test	NOT CHECK	فحص علي الطريق
05.C Visual Gear Box Condition	OIL WET	حالة الجير النظرى
<b>06 Chassis Condition</b>		<b>الشاصي</b>
06.A Chassis	CHASSIS VISABLE AREA OK	الشاسيه
<b>07 Seats Condition</b>		<b>المقاعد</b>
07.A Seat Condition	DRIVER SEAT PORTION DAMAGED	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.