CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2906128
Transaction Date	27 Oct 2026, 13:01:14
Site Name	840 - Emirates Auctions
Transaction Number	67137098 (CC10010) (CC10011)



Vehicle Details

Chassis Number	JN8AZ08W78*******
Specification	GCC Specification
Make	Nissan
Model	Murano
Model Year	2008
Color	Black
Mileage	158406 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED,EXCEPT ROOF TRUNK,MINOR DENTS SCRATCHES,PORTION FADED RUSTY	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.D Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.E Bumper	MISALIGN PORTION CRACKED	دعامية
01.F Bonnet	REFITTED,SHOCK WEAK	غطاء المحرك
01.G Trunk	FIBER PAINT NOT CHECK,NOT OPEN	صندوق
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETE COVERED ,OILY MUDDY NOT VISIBLE PROPERLY,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	EXTRA COVER PORTION WORN OUT,DRIVER SEAT SIDE COVER DAMAGED	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
05.B Propeller Shaft	MISSING	ناقل الحركة
05.C Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2020 CRACK EXPIRED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2020 CRACK EXPIRED	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED ALL LIGHT NOT CHECK	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Arms	LOWER ARM BUSHES CRACK	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT .	ربلة المقود
10.B Steering Box	OIL LEAK .	جهاز المقود
10.C Axle	BOOT CUT /.	اكسلات
11 Interior Condition		الحاله الداخليه
11.A Other	CENTER CONSOLE BOX DAMAGED.INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
11.B AC Condition	NOT CHECK,GRILL PORTION CRACK	المكيف
11.C Roof Light	ASSEMBLY LOOSE	أنارة السقف
11.D Dash Board	PORTION CRACK WORN OUT	لوحة القياده
11.E Roof Ceiling	PORTION DIRTY WORN OUT	بطانه السقف
11.F Sun Visor	LEFT SIDE DAMAGED,RIGHT MINOR LOOSE	حاجب الشمس
11.G Door Panel	PORTION WORN OUT	لوحة بطانة الباب
11.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.I Gear Shifting Lever	KNOB WORN OUT,SHIFT LOCK COVER MISSING	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae