



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **08 Sep 2021, 11:36:35**  
 Transaction Number **47049488 (CC10006)** Queue Number **312309**



Chassis Number **5FNYP18166B700670**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **Honda**  
 Model **MRV**  
 Model Year **2006**  
 Color **Black**  
 Mileage **397723**

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Fenders	FRONT BOTH SIDE REPAINTED	مدكار
01.B Doors	FRONT RIGHT SIDE & REAR TRUNK PORTION REPAIRED, REPAINTED	أبواب
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Bumper	REPAINTED & MISALIGN	دعامية
01.E Bonnet	REPAIRED & REPAINTED	غطاء المحرك
01.F Floor	FRONT FENDER FRAME, BUMPER FRAME , RADITOR SUPPORT , BULK HEAD REPAIRED	الارضية
01.G Other	REAR TRUNK SHOCK WEAK	اخرى
01.H Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
<b>02 Chassis Condition</b>		<b>الشاسي</b>
02.A Chassis	FRONT CHASSIS OILY MUDY VISABLE AREA OK	الشاسيه
<b>03 Engine Condition</b>		<b>المحرك</b>
03.A Mount	BUSHES DRY CRACK	كرسي
03.B Other	OIL LEAK	اخرى
<b>04 Seats Condition</b>		<b>المقاعد</b>
04.A Other	OK	اخرى
<b>05 Transmission Condition</b>		<b>الجير</b>

DEFECT	REMARKS	
05.A Gear Box	OIL LEAK	الجير
05.B Gear Box Mount	BUSHES CRACKED	كرسي الجير
05.C Propeller Shaft	PROPELLER SHAFT MISSING	ناقل الحركة
<b>06 Brake Condition</b>		<b>الفرامل</b>
06.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
<b>07 Suspension System</b>		<b>ممتص الصدمات</b>
07.A Shock Absorber	WEAK	ممتص الصدمات
07.B Arms	FRONT BOTH SIDE LOWER ARMS BUSHES CUT & GETTING RUSTY	ازرع
07.C Suspension Subframe	SUSPENTION SUB FRAME GETTING RUSTY & BOTH SIDE BUSHES CRACKED	
<b>08 Steering Condition</b>		<b>المقود</b>
08.A Steering Oil	POWER STEERING LEAKING	زيت المقود
08.B Steering Box	LEAKING	جهاز المقود
08.C Rack Pinion	LEAKING	مسطرة المقود
08.D Tie Rod End	BUSHES CRACKED	مؤخرة الرودادات
<b>09 Interior Condition</b>		<b>الاجزاء الداخلية</b>
09.A Other	REAR LEFT SIDE & FRONT RIGHT SIDE GLASS WINDOW NOT WORKING	اخرى
09.B Mirror	OK	المرابا
09.C AC Condition	OK	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.