

Queue Number 2922677

Transaction Date 30 Oct 2026, 14:53:42

Site Name
840 - Emirates AuctionsTransaction Number
36393440 (CC10009) (CC10025)

Vehicle Details

Chassis Number	WAUCC8R0D*****
Specification	GCC Specification
Make	Audi
Model	Q5
Model Year	2013
Color	Grey
Mileage	254260 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR LEFT SIDE REPAINTED PORTION REPAIRED , FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	REPAIR BOTH SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDE BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS COVERED, COVERS PORTION DAMAGED DENT	الارضية
01.F Bumper	MISALIGN , GRILL BRACKET DAMAGED PORTION LOOSE , HOOK COVER MISSING	دعامية
01.G Windshield	FRONT SPOT CRACK	زجاج
01.H Bonnet	SHOCK NOT WORKING	غطاء المحرك
01.I Trunk	LUGGAGE SHADE MISSING	صندوق
01.J Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FULLY OILY MUDDY DIRTY & COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	STEAM WASH & REMOVE ALL UNDER FLOOR CHASSIS COVERS FOR RECHECK PROPERLY	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK DRIPPING OPEN REFITTED SHAKING GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Transmission Condition

الجير

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	OIL LEAK OPEN REFITTED MINOR JERKING, DELAY SHIFTING	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

05 Tires and Rims Condition

الاطارات

05.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
05.D Spare Tire &Tools	TOP COVER MISSING	الاطار الاحتياطي و العدة

06 Lights

الاضاءة

06.A Head Light	LENS FADED , HIGH BEAM NOT WORKING	الاضاءة الرئيسية
06.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
06.C Brake Light	SWITCH NOT RELEASING	نور الفرامل
06.D Fog light	LEFT SIDE NOT WORKING	كشاف الضباب

07 Interior Condition

الحالة الداخليه

07.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
07.B Mirror	RIGHT SIDE ADJUSTMENT NOT WORKING	المرايا
07.C AC Condition	OK	المكيف
07.D Dash Board	LEATHER REPLACED	لوحة القيادة
07.E Roof Ceiling	PORTION LOOSE	بطانه السقف
07.F Sun Visor	BOTH SIDE BRACKET DAMAGED LOOSE	حاجب الشمس
07.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
07.H Sunroof	CURTAIN DAMAGED	فتحت سقف
07.I Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae

