

Queue Number 2869538

Transaction Date 15 Oct 2026, 12:31:50

Site Name
840 - Emirates AuctionsTransaction Number
81160607 (CC10009) (CC10012)

Vehicle Details

Chassis Number	SALWA2EF2E*****
Specification	GCC Specification
Make	Range Rover
Model	Sport
Model Year	2014
Color	Gold
Mileage	297080 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
-----------	---------	--------

01 Body

جسم المركبة

01.A Fenders	REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR CHASSIS FULLY COVERED CHECKED VISIBLE AREA ONLY	الارضية
01.E Bumper	MISALIGN , PORTION CRACK	دعامية
01.F Bonnet	REFITTED	غطاء المحرك
01.G Sign of front accident	FRONT BUMPER BULK HEAD ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FULLY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	REMOVE ALL UNDER COVER FOR RECHECK PROPERLY	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	MINOR OIL LEAK PARTS REFITTED GETTING RUSTY, ENGINE CAP MISSING	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	PARTS REFITTED, MINOR JERKING	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

05 Tires and Rims Condition

الاطارات

Condition	Remarks	الحالة
05.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Warning Light	WARNING MESSAING	ضوء تحذير
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CRACKED	ازرع
07.B Other	SUSPENSION REFITTED	اخرى
07.C Hydraulic System	FUALT/ NOT WORKING PROPERLY	النظام الهيدروليكي
08 Interior Condition		الحالة الداخلية
08.A AC Condition	OK	المكيف
08.B Roof Ceiling	REFITTED	بطانة السقف
08.C Sun Visor	LEFT SIDE LOOSE	حاجب الشمس

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae