

Queue Number 2565548

Transaction Date 23 Jul 2026, 16:42:09

Site Name
840 - Emirates AuctionsTransaction Number
50500385 (CC10006) (CC10019)

Vehicle Details

Chassis Number	MHFBU8FS8K*****
Specification	GCC Specification
Make	Toyota
Model	Fortuner
Model Year	2019
Color	White
Mileage	200380 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT LEFT SIDE REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED, MINOR DENTS & SCRATCHES, PORTION RUSTY, PORTION FADED	الصبغ
01.C Rusty	UNDER BODY PARTS, SUSPENSION GETTING RUSTY	صدأ
01.D Bumper	MISALIGN, PORTION DAMAGED	دعامية
01.E Bonnet	REFITTED	غطاء المحرك
01.F Other	FRONT BUMPER FRAME , FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT REPAIRED	اخرى
01.G Sign of front accident		وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FRAME OILY, MUDDY, GETTING RUSTY, FRONT RIGHT SIDE END, BODY MOUNT REPAIRED	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Mount	BUSHES CUT	كرسي
03.B Engine Visual Condition	MISFIRING, REFITTED, OIL LEAK, PARTS RUSTY	الحالة النظرية للمحرك

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	JERKING, OIL LEAK, REFITTED, PARTS RUSTY	الحالة النظرية للجير
04.B Gear Box Mount	BUSH CRACKED	كرسي الجير

Condition	Remarks	الحالة
04.C Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06 Suspension System		ممتص الصدمات
06.A Arms	BUSHES CUT	ازرع
06.B Ball Joint	BOOT CUT	مفصل كروي
07 Interior Condition		الحالة الداخلية
07.A Other	INTERIOR PARTS GETTING RUSTY,SIGN OF FLOODED	اخرى
07.B Mirror	CENTER MIRROR PORTION LOOSE	المرآيا
07.C AC Condition	NOT COOLING	المكيف
07.D Roof Light	LEFT SIDE COVER LIGHT MISSING	أنارة السقف
07.E Dash Board	GLOVE BOX DAMAGED	لوحة القيادة
07.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
07.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae