





Test Certificate

Site Number	: 840-TASJEEL EM AUCTION	Plate Code	: 0
Transaction Number	: 19142601	Plate Category	: PRIVATE
Transaction Date	: 08 FEB 2020 09:21:22	Plate Number	: 951 EA
Queue Number	: 142940	Import Doc. Ref.	:
Chassis Number	: JS3TD94V784109511	Manufacturer/Model	: SUZUKI/GRAND VITARA
Engine Number	:	Model Year	: 2008
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.15 - Suspension Crack Or Bend, Bushes		التوصيلات
02.17 - Gear Box Mounting		كراسي ناقل الحركة
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
04.04 - Rear Left And Right Hand Tires		الاطارات الخلفية
05 Body		الهيكل
05.02 - Paint		الصبغ
06 General Items		الاشياء العامة
06.12 - Seats Condition And Seats Fixing		المقاعد وحالتها وتثبيتها
06.14 - Transmission Condition		حالة ناقل الحركة
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
06.21 - Battery Condition		حالة البطارية
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.06 - Chassis Ok		الشاصي جيد
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.18 - A/C Not Cooling		عطل في المكيف
09.25 - Body Repainted		أثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.



Test Certificate

Site Number	: 840-TASJEEL EM AUCTION	Plate Code	: 0
Transaction Number	: 19142601	Plate Category	: PRIVATE
Transaction Date	: 08 FEB 2020 09:21:22	Plate Number	: 951 EA
Queue Number	: 142940	Import Doc. Ref.	:
Chassis Number	: JS3TD94V784109511	Manufacturer/Model	: SUZUKI/GRAND VITARA
Engine Number	:	Model Year	: 2008
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition