



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	15 Jan 2023, 17:00:48
Transaction Number	60011038 (CC10010)	Queue Number	657300



Chassis Number	KMHTC6AD7HU310042
Engine Number	
Vehicle Class	Car
Manufacturer	Hyundai
Model	Veloster
Model Year	2017
Color	White
Mileage	001 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	Imported

DEFECT	REMARKS	
01 Engine Condition المحرك		
01.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK,KEY MISSING,REFITTED OIL LEAK	حالة المحرك النظرى
02 Transmission Condition الجير		
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Visual Gear Box Condition	NOT CHECK,REFITTED OIL LEAK	حالة الجير النظرى
03 Interior Condition الحاله الداخليه		
03.A AC Condition	NOT CHECK	المكيف
03.B Air Bag	DAMAGED	وسائد هوائية
03.C Odometer reading	NOT CHECK	قراءة عداد المسافات
04 Body جسم المركبة		
04.A Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,PORTION FADED,	الصبغ
04.B Door Handle & Lock	RIGHT SIDE OUTER DOOR HANDLE DAMAGED,MISSING	مقابض الأبواب والأقفال
04.C Bumper	MISALIGN,PORTION DAMAGED	دعامية
04.D Rusty	UNDER BODY PARTS SUSPENSION GETTING RUSTY	صدأ

DEFECT	REMARKS	
04.E Floor	UNDER FLOOR COVERED,RUST PROOFED,CHECKED VISIBLE AREA ,PORTION DENT	الارضية
04.F Bonnet	REFITTED	غطاء المحرك
04.G Other	FRONT FENDER FRAME ,BULK HEAD,BUMPER FRAME RADIATOR SUPPORT REPAIRED	اخري
04.H Sign of front accident		وجود مؤشر لحادث في المقدمة
04.I Fenders	FRONT REFITTED	مدكار
05 Lights		الاضاءة
05.A Head Light	LENS PORTION FADED,ALL LIGHT NOT CHECK	الاضاءة الرئيسية
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2020 CRACKED ,	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الخلفي
07 Suspension System		ممتص الصدمات
07.A Arms	LOWER ARM BUSH CRACKED	ازرع
07.B Suspension Subframe	SUBFRAME DENT & CRACKED	
07.C Ball Joint	BOOT CUT	مفصل كروي
08 Chassis Condition		الشاصي
08.A Chassis	FRONT BOTH SIDE CHASSIS & CHASSIS JOINT AREA REPAIRED	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.