CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2937820
Transaction Date	03 Nov 2026, 12:49:43
Site Name	840 - Emirates Auctions
Transaction Number	71867296 (CC10009) (CC10019)



Vehicle Details

Chassis Number	KMFWBX7KBE*******
Specification	Imported
Make	Hyundai
Model	Starex
Model Year	2014
Color	Silver
Mileage	148022 Km
Fuel Type	Diesel
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,	الصبغ
01.C Rusty	UNDER BODY PARTS CHASSIS SUSPENSION RUSTY	صدأ
01.D Floor	REAR FLOOR PORTION REPAIRED/ PORTION DENT	الارضية
01.E Bumper	MISALIGN	دعامية
01.F Windshield	FRONT CRACKED	زجاج
01.G Bonnet	REFITTED	غطاء المحرك
01.H Pillars	LEFT SIDE C/ PILLAR ROCKER PANEL REPAIRED	القوائم
01.I Sign of back accident	BACK PANEL QUARTER PANEL REPAIRED	وجود مؤشر لحادث في الخلف
01.J Vehicle Color	GREY	لون المركبة
02 Chassis Condition		الشاصي
02.A Chassis	REAR CHASSIS EXTENSION END CROSS MEMEBER REPAIRED, GETTING RUSTY	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL WET REFITTED GETTING RUSTY MINOR SHAKING	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	EXTRA COVER PORTION DAMAGED	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06.D Spare Tire &Tools	MISSING	الاطار الاحتياطي و العدة
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CUT	ازرع
08 Steering Condition		المقود
08.A Other	HAVE PLY	اخري
09 Interior Condition		الحاله الداخليه
09.A Other	INETRIOR PARTS GETTING RUSTY, SIGN OF FLOODED & CENTER CONSOLE BOX COVER LOOSE	اخري
09.B Mirror	LEFT SIDE FOLDING ADJUSTMENT NOT WORKING	المرايا
09.C AC Condition	OK	المكيف
09.D Audio	LOOSE	صوتيات
09.E Roof Ceiling	PORTION WORN OUT REAR MODIFIED	بطانه السقف
09.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae