CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2905901
Transaction Date	26 Oct 2026, 12:51:15
Site Name	840 - Emirates Auctions
Transaction Number	12122841 (CC10021) (CC10021)



Vehicle Details

Chassis Number	KMHRB8A30M*******
Specification	Imported
Make	Hyundai
Model	Venue
Model Year	2021
Color	Red
Mileage	93258 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY REPAINTED PORTION REPAIRED (EXCEPT ROOF)DENTS, SCRATCHES	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY .	صدأ
01.C Floor	NEED TO REMOVE BOTH SIDE FENDER COVER FOR PROPER INSPECTION	الارضية
01.D Bumper	MISALIGN	دعامية
01.E Pillars	PILLAR REPAIRED	القوائم
01.F Sign of front accident	BUMPER FRAME, BULKHEAD, RADIATOR SUPPORT, FENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة
01.G Sign of back accident	BACK PANEL , BUMPER FRAME REPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED,MUDDY,PORTION DENT CHECKED VISIBLE AREA ONLY	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	REFITTED PARTS GETTING RUSTY , MINOR OIL LEAK	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	REFITTED PARTS GETTING RUSTY , MINOR OIL LEAK	الحالة النظريه للجير
04.B Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي

Condition	Remarks	الحالة
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06 Brake Condition		الفرامل
06.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CRACK	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
08 Interior Condition		الحاله الداخليه
08.A Other	CENTER CONSOLE BOX COVER WORN OUT , INETRIOR PARTS GETTING RUSTY	اخري
08.B AC Condition	NO COOLING	المكيف
08.C Door Panel	WORN OUT	لوحة بطانة الباب
08.D Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae