



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>04 Dec 2022, 16:53:15</b>
Transaction Number	<b>47373247 (CC10008)</b>	Queue Number	<b>635625</b>



Chassis Number	<b>JTGJX02P555000874</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Toyota</b>
Model	<b>Hiace</b>
Model Year	<b>2005</b>
Color	<b>White</b>
Mileage	<b>285351 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES PORTION RUSTY,BODY HAVE MODIFIED HOLE	الصبغ
01.B Roof	MODIFIED HOLE	السقف
01.C Rusty	UNDER BODY PART , GETTING RUSTY	صدأ
<b>02 Interior Condition</b>		<b>الحاله الداخليه</b>
02.A Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
02.B Other	INTERIOR HAVE SAFETY GRILL FOR D/POLICEE USE BEFORE	اخرى
02.C AC Condition	OK	المكيف
02.D Dash Board	RIGHT SIDE CONSOLE BOX MISSING &DASHBOARD HAVE EXTRA FITTING ,HOLE &GEAR LEVER DUST COVER DAMAGED	لوحة القيادة
<b>03 Lights</b>		<b>الاضاءة</b>
03.A Head Light	LENS FADED	الاضاءة الرئيسية
<b>04 Transmission Condition</b>		<b>الجير</b>

DEFECT	REMARKS	
04.A Visual Gear Box Condition	REFITTED	حالة الجير النظري
04.B Gear Box Mount	MOUNT BUSHES CRACKED	كرسي الجير
04.C Road Test	NOT CHECKED	فحص علي الطريق
<b>05 Suspension System</b>		<b>ممتص الصدمات</b>
05.A Leaf Spring	BUSHES CRACKED	
05.B Arms	LOWER ARM BUSHES CRACKED	ازرع
<b>06 Seats Condition</b>		<b>المقاعد</b>
06.A Seat Condition	DRIVER SEAT PORTION CUT	حالة المقاعد
<b>07 Tires and Rims Condition</b>		<b>الاطارات</b>
07.A Front Tyre	BOTH SIDE 2019 CRACKED	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2019 CRACKED	الاطار الخلفي
<b>08 Engine Condition</b>		<b>المحرك</b>
08.A Visual Engine Condition	OIL LEAK,SHAKING ,REFITTED	حالة المحرك النظري
08.B Mount	MOUNT BUSHES CRACKED	كرسي
<b>09 Chassis Condition</b>		<b>الشاسي</b>
09.A Chassis	OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.