

Queue Number 2840699

Transaction Date 06 Oct 2026, 16:33:36

Site Name
840 - Emirates AuctionsTransaction Number
56514626 (CC10009) (CC10012)

Vehicle Details

Chassis Number	WBA6A0106F*****
Specification	GCC Specification
Make	BMW
Model	640 I
Model Year	2015
Color	White
Mileage	98542 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE FIBER PAINT NOT CHECK , SING REFITTED & REAR RIGHT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	RIGHT SIDE BOTH REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS COVERED OILY	الارضية
01.F Bumper	REAR RIGHT SIDE REFLECTOR COVER DAMAGED	دعامية
01.G Windshield	REAR CRACKED	زجاج
01.H Trunk	FIBER PAINT NOT CHECK	صندوق
01.I Door Handle & Lock	FRONT LEFT SIDE AUTO NOT WORKING	مقابض الأبواب والأقفال
01.J Sign of front accident	FRONT BUMPER FRAME BULK HEAD ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Other	AIR INTAKE PIPE DAMAGED	اخرى
03.B Engine Visual Condition	OIL LEAK OPENR EFITTED ABNORMAP NOISY HOLE COVER MISSING, GETTING RUSTY	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	PORTION CUT	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR OIL EAK OPEN REFITTED GETTING RUSTY JERKING	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	RIGHT SIDE 2023 CRACK , LEFT SIDE 20	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES , FRONT RIGHT HUB COVER LOGO MISSING	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	SWITCH MELTED , WORN OUT	الاضاءة الرئيسية
07.B Tail Light	BOTH SIDE , CENTER CRACKED	الضوء الخلفي
08 Brake Condition		الفرامل
08.A Hand Brake	SWITCH CRACK , REPAIRED	فرامل اليد
09 Suspension System		ممتص الصدمات
09.A Arms	LOWER ARM BUSHES CUT	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي
10 Interior Condition		الحالة الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY , (SIGN OF FLOODED)	اخرى
10.B Mirror	LEFT SIDE FOLDING NOT WORKING , PORTION LOOSE	المرايا
10.C AC Condition	OK , GRILL DAMAGED	المكيف
10.D Audio	SCREEN MINOR FADED	صوتيات
10.E Dash Board	LEATHER LOOSE	لوحة القيادة
10.F Roof Ceiling	PORTION LOOSE	بطانه السقف
10.G Door Panel	LEATHER PORTION LOOSE , REAR RIGHT SIDE CIGARETTE COVER MISSING	لوحة بطانة الباب
10.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.I Sunroof	NOT WORKING	فتحت سقف
10.J Engine Start Button	BUTTON FADED	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
للتسجيل من عدمه

للسكاوي والمقترحات يمكنك التواصل معنا عبر
wecare@carscheck.ae