

Queue Number 2866342

Transaction Date 14 Oct 2026, 16:54:43

Site Name
840 - Emirates AuctionsTransaction Number
19957441 (CC10009) (CC10012)

Vehicle Details

Chassis Number	JF2GT2LD7K*****
Specification	GCC Specification
Make	Subaru
Model	XV 2.0
Model Year	2019
Color	Grey
Mileage	112680 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	LEFT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	LEFT SIDE REPAINTED PORTION REPAIRED , REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	CENTER FLOOR FRONT CHASSIS COVERED CHECKED VISIBLE AREA ONLY	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Pillars	LEFT SIDE PILLAR ROCKER PANEL REPAIRED , BOTH SIDE B / PILLAR PORTION DENT	القوائم
01.H Trunk	MISALIGN	صندوق
01.I Sign of front accident	FRONT BUMPER FRAME BEND , BULK HEAD ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
01.J Sign of side accident		وجود مؤشر لحادث في الجانب

02 Chassis Condition

الشاسي

02.A Chassis	FRONT CHASSIS COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Chassis Number	CHASSIS NUMBER STICKER REFITTED , PORTION DAMAGED	رقم القاعدة

03 Engine Condition

المحرك

03.A Engine Visual Condition	SIGN OF OIL WET, PARTS GETTINT RUSTY	الحالة النظرية للمحرك
------------------------------	--------------------------------------	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	FRONT RIGHT SIDE BOLT LOOSE	حالة المقاعد
---------------------	-----------------------------	--------------

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	PARS GETTING RUSTY, MINOR JEKRING	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2022 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022 CRACK	الاطار الخلفي
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CRACKED	ازرع
08 Interior Condition		الحالة الداخليه
08.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
08.B AC Condition	OK	المكيف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae