



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	20 Jul 2022, 13:20:35
Transaction Number	33142317 (CC10006)	Queue Number	312309



Chassis Number	KMHTG6AFXKU004000
Engine Number	
Vehicle Class	Car
Manufacturer	Hyundai
Model	Veloster
Model Year	2019
Color	Grey
Mileage	38839 Miles
Fuel Type	Petrol
No. Of Cylinders	4
Specification	USA Imported

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REPAINTED & REFITTED	مدكار
01.B Doors	LEFT SIDE PORTION REPAIRED,REPAINTED	أبواب
01.C Bonnet	PORTION REPAIRED,REPAINTED & REFITTED	غطاء المحرك
01.D Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
01.E Sign of side accident		وجود مؤشر لحادث في الجانب
01.F Other	FRONT FENDER FRAME, RADITOR SUPPORT ,BUMPER FRAME, BULK HEAD REPAIRED	اخرى
01.G Rusty	UNDER BODY PARTS, SUSPENSION GETTING RUSTY	صدأ
02 Seats Condition		المقاعد
02.A Seat Belt	FRONT BOTH SIDE NOT WORKING	حزام الأمان
03 Transmission Condition		الجير
03.A Road Test	NOT CHECK	فحص على الطريق
04 Interior Condition		الحالة الداخلية
04.A AC Condition	OK	المكيف
05 Battery Condition		حالة البطارية

DEFECT	REMARKS	
05.A Battery bracket	MISSING	حامل البطارية
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2018	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2018	الاطار الخلفي
06.C Spare Tire &Tools	MISSING	الاطار الاحتياطي و العدة
07 Suspension System		ممتص الصدمات
07.A Arms	LOWER ARM BUSHES CRACKED	ازرع
08 Chassis Condition		الشاسي
08.A Chassis	FRONT BOTH SIDE CHASSIS REPAIRED	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



✓ PASS

Vehicle
Registration



Plate Details :	--
Chassis No :	KMHTG6AFXKU004000
Vehicle Make :	HYUNDAI
Vehicle Model :	VELOSTER
Vehicle Class :	Light Vehicle
Body Type :	HATCHBACK
Fuel :	Benzene
Color :	Gray
Drive Direction :	Left Hand Side
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	62502 Kms.
Origin : South Korea	Model Year : 2019
Gear Type : Automatic	Engine Size : 2000 CC
Engine No : nil	Horse --
Axles No : 2	Power :
No Of 3	Cylinders : 4
Doors :	No Of Seats : 5
G. V. W. : 1950 Kgs.	Empty 1650 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17180320
Inspection Date :	12-07-2022
Certificate Print Date :	12-07-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Qusais
Total Time Taken :	3 min 52 sec
Appointment Ref Number :	--
Start 12:24	End Time : 12:28
Time :	Token No. : 337
Lane : 08	Prints No : 1
Attempt : 2	

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)



48 KM

Distance per
year



4 L

Fuel consumed
per year



13 AED

Fuel cost per
year



0.1 ton

Carbon footprint
per year

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	2000	1600	

Inspection Remarks:

HAVE PASSES CCM REPORT FRONT BOTH SIDE CHASSIS HEATED AND REPAIRED W/O 2022-07-07-9 FRONT BOTH SIDES BULK HEAD,FENDER FRAME,INNER MEMBER REPAIRED.UNDERNEATH PORTIONS COVERED, BODY MINOR PAINT SCRATCHES.

Payment Details

Inspection Performed by 31218	Payment Method Cash	Transaction Number 17180320	Service Fees AED 70 Collected on 12/07/2022
Parking Slot No --	Service Name Registration Test	Attempt 2	Received by Maitha Alsuwidi

1 This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتسجيل الفنى للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

