





Test Certificate

Site Number	: 840-TASJEEL EM AUCTION	Plate Code	: 0
Transaction Number	: 18811074	Plate Category	: PRIVATE
Transaction Date	: 22 DEC 2019 14:55:38	Plate Number	: 3942 EA
Queue Number	: 127290	Import Doc. Ref.	:
Chassis Number	: 6G1MK52B09L233942	Manufacturer/Model	: CHEVROLET/CAPRICE
Engine Number	:	Model Year	: 2009
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.10 - Ties Rods, Bushes, Centerlink, Left And Right		ربلات ذراع التوجيه
02.15 - Suspension Crack Or Bend, Bushes		التوصيلات
02.17 - Gear Box Mounting		كراسي ناقل الحركة
03 Brake System		نظام الفرامل
03.01 - Brake Efficiency Front Wheels Left And Right Hands		قوة فرامل المحور الامامي
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
04.07 - Rims		الرنجات
05 Body		الهيكل
05.02 - Paint		الصبغ
06 General Items		الاشياء العامة
06.12 - Seats Condition And Seats Fixing		المقاعد وحالتها وتثبيتها
06.14 - Transmission Condition		حالة ناقل الحركة
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
09 Auction		الفحص الكامل
09.06 - Chassis Ok		الشاسي جيد
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.18 - A/C Not Cooling		عطل في المكيف
09.24 - Digital Display Damaged/Warning Lights		عطل في لوحة التحكم الالكتروني



Test Certificate

Site Number	: 840-TASJEEL EM AUCTION	Plate Code	: 0
Transaction Number	: 18811074	Plate Category	: PRIVATE
Transaction Date	: 22 DEC 2019 14:55:38	Plate Number	: 3942 EA
Queue Number	: 127290	Import Doc. Ref.	:
Chassis Number	: 6G1MK52B09L233942	Manufacturer/Model	: CHEVROLET/CAPRICE
Engine Number	:	Model Year	: 2009
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

09.25 - Body Repainted	BODY PORTIONS REPAINTED	أثر صدىغ في المركبة
The Test Certificate Shows the test Result at the time of inspection only.		