

Queue Number 2579245

Transaction Date 25 Jul 2026, 12:47:54

Site Name
840 - Emirates AuctionsTransaction Number
89544947 (CC10013) (CC10013)

Vehicle Details

Chassis Number	VSKDD3C27K*****
Specification	GCC Specification
Make	Nissan
Model	Navara
Model Year	2019
Color	White
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED, DENT & SCRATCHES, PORTION FADED, PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN, PORTION DAMAGED	دعامية
01.E Fuel Tank	DENT	خزان الوقود
01.F Sign of front accident	FRONT BUMPER FRAME, BULKHEAD, RADIATOR SUPPORT, FENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FRAME MUDDY DIRTY GETTING RUSTY PORTION DENT	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY KEY MISSING	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
---------------------	-----------------	--------------

05 Exhaust System

نظام العادم

05.A Other	DENT	اخرى
------------	------	------

06 Transmission Condition

الجير

Condition	Remarks	الحالة
06.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظرية للجير
06.B Road Test	NOT CHECK	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2022 CRACKED	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2022 CRACKED	الاطار الخلفي
08 Lights		الاضاءة
08.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED & LEFT SIDE DAMAGED	الاضاءة الرئيسية
09 Brake Condition		الفرامل
09.A Disc&Drum	RUSTY	دسك و طنابير الفرامل
10 Suspension System		ممتص الصدمات
10.A Leaf Spring	MISALIGN BUSHES DRY CRACK	اخرى
10.B Other	ALL BUSHES DRY CRACK	
11 Interior Condition		الحالة الداخلية
11.A Other	INTERIOR PARTS RUSTY,SIGN OF FLOODED	اخرى
11.B Mirror	CENTER MIRROR PORTION FADED	المرآيا
11.C AC Condition	NOT CHECKED	المكيف
11.D Dash Board	PORTION DAMAGED	لوحة القيادة
11.E Odometer reading	NOT CHECKED	قراءة عداد المسافات
11.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
12 Battery Condition		حالة البطارية
12.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on

لشكاوي والمقترحات يمكنك التواصل معنا عبر

