

Queue Number 2735647

Transaction Date 09 Sep 2026, 12:56:11

Site Name
840 - Emirates AuctionsTransaction Number
81407526 (CC10009) (CC10012)

Vehicle Details

Chassis Number	SCBBF53W0C*****
Specification	GCC Specification
Make	Bentley
Model	Flying Spur
Model Year	2012
Color	White
Mileage	120069 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	12

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR FULLY COVERED, PORTION DENT RUST PROOFED	الارضية
01.F Bonnet	REFITTED , SHOCK WEAK NOT WORKING	غطاء المحرك
01.G Door Handle & Lock	REAR LEFT SIDE HANDLE PORTION LOOSE	مقابض الأبواب والأقفال

02 Chassis Condition الشاسي

02.A Chassis	CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Chassis Number	VIN STICKER PORTION FADED	رقم القاعدة

03 Engine Condition المحرك

03.A Engine Visual Condition	SIGN O OIL WET, PARTS REFITTED GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition المقاعد

04.A Seat Condition	EXTRA COVER , PORTION CUT , FRONT BOTH SIDE ADJUSTMENT SWITCH STRIP COVER PORTION MISSING	حالة المقاعد
---------------------	---	--------------

05 Transmission Condition الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	PARTS GETTING RUSTY, MINOR JERKING	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2022	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCVRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED , LEFT SIDE STRIP PORTION MISSING	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Interior Condition		الحالة الداخليه
08.A Other	(INTERIOR REFITTED)	اخرى
08.B Mirror	BOTH SIDE AUTO NOT WORKING , PORTION LOOSE	المرآيا
08.C AC Condition	OK	المكيف
08.D Power Window Switch And Glass	REAR RIGHT SIDE SWITCH LOOSE	مفتاح النافذه و الزجاج
08.E Audio	SCREEN GETTING FADED	صوتيات
08.F Dash Board	LEATHER REPLACED	لوحة القيادة
08.G Roof Ceiling	REFITTED , PORTION LOOSE	بطانه السقف
08.H Sun Visor	STAND DAMAGED	حاجب الشمس
08.I Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.J Engine Start Button	ENGINE START STRIP COVER MISSING , KEY PORTION DAMAGED	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae