CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2997773
Transaction Date	16 Nov 2026, 16:52:13
Site Name	840 - Emirates Auctions
Transaction Number	34656698 (CC10013) (CC10011)



Vehicle Details

Chassis Number	JTHBK1GG2D*******
Specification	GCC Specification
Make	Lexus
Model	ES 350
Model Year	2013
Color	White
Mileage	139633 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REAR LEFT REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR COVERED PORTION DIRTY MUDDY MINOR DENT	الارضية
01.E Bumper	MISALIGN,GRILL PORTION CRACK	دعامية
01.F Bonnet	PORTION REPAIRED REPAINTED	غطاء المحرك
01.G Pillars	INNER SAFETY COVER WORN OUT	القوائم
01.H Trunk	OPEN WITH KEY ONLY	صندوق
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED MUDDY DIRTY CHECK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL PAN DENT , MUDDY DIRTY , ABNORMAL NOISY , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	MINOR JERKING , DIRTY MUDDY PARTS GETTING RUSTY	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات

Condition	Remarks	الحالة
05.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06 Lights		الاضاءة
06.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
06.B Brake Light	LEFT SIDE NOT WORKING	نور الفرامل
07 Suspension System		ممتص الصدمات
07.A Shock Absorber	SIGN OF LEAK UPPER MOUNT RUBBER CRACK	ممتص الصدمات
07.B Arms	ARM BUSHES DRY CRACK	ازرع
07.C Ball Joint	BOOT CUT	مفصل كروي
07.D Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CUT	مؤخرة الرودات
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY REFITTED	اخري
09.B Mirror	LEFT SIDE VIEW MIRROR INDICATOR COVER DAMAGED	المرايا
09.C AC Condition	OK	المكيف
09.D Power Window Switch And Glass	NOT WORKING PROPERLY	مفتاح النافذه و الزجاج
09.E Dash Board	LEATHER REPLACED	لوحة القياده
09.F Sun Visor	RIGHT SIDE LOOSE LOCK,MIRROR DAMAGED	حاجب الشمس
09.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.H Sunroof	NOT WORKING PROPERLY BEADING LOOSE,CURTAIN STUCK	فتحت سقف
09.I Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae