



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	28 Apr 2022, 14:46:37
Transaction Number	41701438 (CC10006)	Queue Number	312309



Chassis Number	JTEHJ09JX65126126
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Land Cruiser GXR
Model Year	2006
Color	White
Mileage	001 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES,PORTION FADED & RUSTY	الصبغ
01.B Bonnet	REFITTED & SHOCK WEAK	غطاء المحرك
01.C Other	FROTNBUMPER FRAME BULK HEAD REPAIRED , FRONT BUMPER FRAME STILL BEND	اخرى
01.D Bumper	FRONT DAMAGED	دعامية
02 Interior Condition		الحاله الداخليه
02.A AC Condition	NOT COOLING	المكيف
02.B Power Window Switch	REAR BOTH SIDE NOT WORKING	مفتاح النافذه
02.C Roof Ceiling	LOOSE	بطانه السقف
02.D Odometer reading	ODOMETER NOT SHOWING PROPERLY	قراءة عداد المسافات
02.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
02.F Other	REAR BOTH SIDE CIGARETTE CONSOLE BOX COVER LOOSE	اخرى
03 Tires and Rims Condition		الاطارات
03.A Front Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الامامي

DEFECT	REMARKS	
03.B Rear Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الخلفي
04 Engine Condition		المحرك
04.A Visual Engine Condition	OIL LEAK & REFITTED	حالة المحرك النظري
04.B Smoke	WHITE SMOKE	دخان
05 Suspension System		ممتص الصدمات
05.A Arms	FRONT LOWER ARM REAR CONTROL ARM BUSHES CRACKED	ازرع
05.B Ball Joint	BOOT CUT	مفصل كروي
06 Transmission Condition		الجير
06.A Visual Gear Box Condition	OIL LEAK & REFITTED	حالة الجير النظري
06.B Road Test	NOT CHECK	فحص علي الطريق
07 Steering Condition		المقود
07.A Axle	BOOT LEAK	اكسلات
07.B Tie Rod End	BOOT CUT	مؤخرة الرودادات
07.C Steering Oil	MINOR OIL LEAK	زيت المقود
08 Lights		الاضاءة
08.A Head Light	LENS FADED, RIGHT SIDE HIGH BEAM NOT WORKING	الاضاءة الرئيسية
08.B Fog light	LEFT SIDE DAMAGED	كشاف الضباب
09 Chassis Condition		الشاسي
09.A Chassis	OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.