

Queue Number

2665912

Transaction Date

20 Aug 2026, 13:51:45

Site Name

840 - Emirates Auctions

Transaction Number

90202037 (CC10009) (CC10012)



Vehicle Details

Chassis Number	1C4RDJDG8G*****
Specification	GCC Specification
Make	Dodge
Model	Durango
Model Year	2016
Color	Silver
Mileage	177778 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT LEFT SIDE REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , GETTING RUSTY	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR PORTION DENT	الارضية
01.E Bumper	MISALIGN	دعامية
01.F Roof	REPAIRED , BOTH SIDE ROOF RAIL REPAIRED	السقف
01.G Bonnet	REFITTED	غطاء المحرك

02 Chassis Condition

الشاسي

02.A Chassis	FRONT RIGHT SIDE EDGE MINOR DENT,OK	الشاسيه
--------------	-------------------------------------	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	MINOR OIL LEAK REFITTED	الحالة النظرية للمحرك
------------------------------	-------------------------	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	FRONT RIGHT SIDE HEADREST PORTION LOOSE	حالة المقاعد
---------------------	---	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	REFITTED, MINOR JERKING	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Suspension System		ممتص الصدمات
07.A Arms	LOWER ARM BUSHES CRACKED	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
08 Interior Condition		الحالة الداخلية
08.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
08.B AC Condition	OK	المكيف
08.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.D Sunroof	CURTAIN BRACKET DAMAGED LOOSE	فتحت سقف
09 Engine Cooling System		نظام تبريد المحرك
09.A Coolant tank	OIL WATER MIXED	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae