



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	22 Nov 2021, 18:02:59
Transaction Number	71214830 (CC10006)	Queue Number	312309



Chassis Number	JMYLYV97WAJ705541
Engine Number	
Vehicle Class	Car
Manufacturer	Mitsubishi
Model	Pajero
Model Year	2010
Color	White
Mileage	268962 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Tires and Rims Condition		الاطارات
01.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
01.C Rims Condition	RIMS HAVE MINOR SCRATCHES	حالة الجنوط
02 Chassis Condition		الشاسي
02.A Chassis	OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Condition	OIL LEAK	حالة المحرك
03.B Smoke	WHITE SMOKE	دخان
04 Transmission Condition		الجير
04.A Road Test	NOT CHECK	فحص علي الطريق
04.B Gear Box	OIL LEAK,JARK	الجير
04.C DIFFERENTIAL	4WD LIGHT NOT WORKING IN DISPLAY	الدفرنشيل
05 Seats Condition		المقاعد
05.A Seat Belt	OK	حزام الأمان
05.B Seat Condition	CRACKED&FRONT RIGHT SIDE ADJUSTMENT NOT	حالة المقاعد

DEFECT	REMARKS	
WORKING		
06 Interior Condition		الحاله الداخليه
06.A AC Condition	REAR AC LOW BLOWER & VENT GRILL BROKEN	المكيف
06.B Dash Board	MINOR CRACKED	لوحة القيادة
06.C Other	CENTER CONSOLE BOX BACK COVER MISSING & GEAR LEVER CONSOLE BOX DUST COVER MISSING	اخرى
06.D Mirror	NOT WORKING PROPERLY	المرآيا
06.E Roof Light	NOT WORKING	أنارة السقف
07 Lights		الاضاءة
07.A Brake Light	INNER CENTER COVER MISSING	نور الفرامل
07.B Head Light	FADED	الاضاءة الرئيسية
07.C Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
08 Wipers and Arms		المساحات
08.A Wiper Arm & Blade	WORNOUT	ازرع المساحات والشفرات
09 Body		جسم المركبة
09.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED, BODY MINOR DENT, SCRATCHES	الصبغ
09.B Fenders	REAR BOTH FENDER REPAINTED & FRONT FENDER MISALIGN	مدكار
09.C Bonnet	MISALIGN	غطاء المحرك
09.D Trunk	REPAINTED, PORTION REPAIRED	صندوق
09.E Floor	BACK PANEL MINOR DENT	الارضية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.