CAR CHECK

# شهادة فحص مركبة
# Vehicle Test Certificate

| | |
|---|---|
| Queue Number | 2899680 |
| Transaction Date | 30 Oct 2026, 14:53:12 |
| Site Name | 840 - Emirates Auctions |
| Transaction Number | 24110204 (CC10026) (CC10026) |




## Vehicle Details

| | |
|---|---|
| Chassis Number | 5NPEC4AC2D******* |
| Specification | Imported |
| Make | Hyundai |
| Model | Sonata |
| Model Year | 2013 |
| Color | Blue |
| Mileage | N/A Miles |
| Fuel Type | Petrol |
| Transmission Type | |
| No. Of Cylinders | 4 |

| Condition | Remarks | الحالة |
|---|---|---|
| **01 Body** | | **جسم المركبة** |
| 01.A Fenders | BOTH LEFT SIDE REPAINTED PORTION REPAIRED | مدكار |
| 01.B Paint | BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED , PORTION RUSTY | الصبغ |
| 01.C Doors | BOTH LEFT SIDE REPAINTED PORTION REPAIRED | أبواب |
| 01.D Rusty | UNDER BODY PARTS ,SUSPENSION GETTING RUSTY | صدأ |
| 01.E Floor | UNDER FLOOR PORTION DENTS, MUDDY | الارضية |
| 01.F Bumper | MISALIGN , PORTION DAMAGE | دعامية |
| 01.G Windshield | FRONT SPOT CRACK | زجاج |
| 01.H Bonnet | STAND STICK MISSING | غطاء المحرك |
| 01.I Sign of front accident | BUMPER FRAME, BULKHEAD, RADIATOR SUPPORT, FENDER FRAME REPAIRED | وجود مؤشر لحادث في المقدمة |
| 01.J Sign of back accident | BACK PANEL, QUATER PANEL, COMPARTMENT , WHEEL ARCK REPAIRED | وجود مؤشر لحادث في الخلف |
| **02 Chassis Condition** | | **الشاصي** |
| 02.A Chassis Extension | LEFT SIDE CHASIS EXTENSION END REPAIRED, DENT | تمديدات الشاسي |
| 02.B Chassis | CHASSIS MUDDY , PORTION DENT | الشاسيه |
| **03 Engine Condition** | | **المحرك** |
| 03.A Engine Visual Condition | ENGINE NOT START ,ALL SYSTEM NOT CHECKED , REFITTED PARTS GETTING RUSTY | الحالة النظريه للمحرك |
| **04 Seats Condition** | | **المقاعد** |

| Condition | Remarks | الحالة |
|---|---|---|
| 04.A Seat Condition | PORTION DAMAGE | حالة المقاعد |
| **05 Transmission Condition** | | الجير |
| 05.A Gear Box Visual Condition | NOT CHECKED REFITTED PARTS GETTING RUSTY | الحالة النظريه للجير |
| 05.B Road Test | NOT CHECK | فحص علي الطريق |
| **06 Tires and Rims Condition** | | الاطارات |
| 06.A Front Tyre | BOTH SIDE CRACK | الاطار الامامي |
| 06.B Rear Tyre | BOTH SIDE CRACK | الاطار الخلفي |
| 06.C Rims Condition | MINOR DENT SCRATCHES | حالة الجنوط |
| **07 Lights** | | الاضاءة |
| 07.A Head Light | LENS FADED, ALL LIGHTS NOT CHECKED | الاضاءة الرئيسية |
| 07.B Tail Light | LEFT SIDE CRACK | الضوء الخلفي |
| **08 Brake Condition** | | الفرامل |
| 08.A Disc&Drum | RUSTY | دسك وطنابير الفرامل |
| **09 Suspension System** | | ممتص الصدمات |
| 09.A Arms | BUSHES CRACK | ازرع |
| 09.B Stabilizer Bar And Link Rod | PORTION WORN OUT | عمود التوازن و مثبت عمود التوازن |
| **10 Steering Condition** | | المقود |
| 10.A Tie Rod End | PORTION WORN OUT | مؤخرة الرودات |
| **11 Interior Condition** | | الحاله الداخليه |
| 11.A Other | CENTER CONSOLE BOX COVER WORN OUT , INETRIOR PARTS GETTING RUSTY , SIGN OF RUSTY | اخري |
| 11.B AC Condition | NOT CHECK | المكيف |
| 11.C FLoor Matting | DIRTY | فرش الأرضيه |
| 11.D Dash Board | DAMAGE | لوحة القياده |
| 11.E Roof Ceiling | PORTION WORN OUT | بطانه السقف |
| 11.F Sun Visor | PORTION WORN OUT | حاجب الشمس |
| 11.G Door Panel | PORTION WORN OUT | لوحة بطانة الباب |
| 11.H Steering Wheel and control buttons | PORTION WORN OUT | عجلة القيادة وازرار التحكم |
| 11.I Gear Shifting Lever | PORTION WORN OUT | ذراع نقل السرعات |
| **12 Engine Cooling System** | | نظام تبريد المحرك |
| 12.A Coolant tank | EMPTY | خزان التبريد |

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
**carcheck.ae/certificate**

## Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

## الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**