

Queue Number 2840694

Transaction Date 06 Oct 2026, 13:43:24

Site Name
840 - Emirates AuctionsTransaction Number
11591407 (CC10009) (CC10012)

Vehicle Details

Chassis Number	ZASPAHBN4K*****
Specification	GCC Specification
Make	Alfa Romeo
Model	Stelvio
Model Year	2019
Color	Black
Mileage	121729 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES & (PAINT THICKNESS HIGH)	الصبغ
01.B Doors	RIGHT SIDE BOTH REPAINTED PORTION REPAIRED	أبواب
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR FRONT CHASSIS NOT VISIBLE	الارضية
01.E Bonnet	OPEN HANDLE LOOSE	غطاء المحرك
01.F Trunk	REFITTED , MISALIGN	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	FRONT CHASSIS FULLY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL WET PARTS REFITTED GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--------------------------------------	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	DRIVER SEAT COVER PORTION CRACK	حالة المقاعد
---------------------	---------------------------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	PARTS GETTING RUSTY, MINOR JERKING	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
07 Lights		الاضاءة
07.A Tail Light	LEFT SIDE PORTION CRACKED	الضوء الخلفي
07.B Warning Light	WARNING LIGHT ON DISPLAY , WARNING MESSAGE	ضوء تحذير
08 Brake Condition		الفرامل
08.A Brake Pedal	SPONGY, WEAK	دواسة الفرامل
08.B Other	ABS WARNING LIGHT	اخرى
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACKED	ازرع
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY, ELECTRIC FUALT, SIGN OF FLOODED	اخرى
10.B Mirror	LEFT SIDE MIRROR INDICATOR LIGHT DAMAGED	المرايا
10.C Roof Ceiling	REPLACED , PORTION LOOSE	بطانه السقف
10.D Door Panel	LEATHER LOOSE	لوحة بطانة الباب
10.E Gear Shifting Lever	MINOR WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae