



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	24 May 2023, 10:50:50
Transaction Number	11381510 (CC10008)	Queue Number	725261



Chassis Number	KNMCC42H3CP883103
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Sunny
Model Year	2012
Color	White
Mileage	315030 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Lights		الاضاءة
01.A Tail Light	LEFT SIDE PORTION CRACKED	الانارة
01.B Head Light	LENS FADED,RIGHT SIDE DAMAGED,LEFT SIDE LOW BEAM NOT WORKING	الاضاءة الرئيسية
02 Interior Condition		الحاله الداخليه
02.A Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
02.B Dash Board	CONSOLE BOX LOCK DAMAGED	لوحة القيادة
02.C Other	CENTER CONSOLE BOX COVER MISSING	اخرى
02.D AC Condition	LOW COOLING	المكيف
02.E Power Window Switch	FRONT LEFT SIDE NOT WORKING,RIGHT SIDE NOT WORKING PROPERLY	مفتاح النافذه
02.F Door Panel	PORTION DAMAGED	لوحة بطانة الباب
02.G Roof Ceiling	PORTION LOOSE	بطانه السقف
03 Tires and Rims Condition		الاطارات
03.A Front Tyre	BOTH SIDE 2020,CRACKED	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2018,CRACKED,EXPIRED	الاطار الخلفي

DEFECT	REMARKS	
04 Body		جسم المركبة
04.A Bumper	PORTION DAMAGED	دعامية
04.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
04.C Fenders	FRONT REFITTED	مدكار
04.D Bonnet	REFITTED	غطاء المحرك
04.E Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES,PORTION FADED,PORTION RUSTY	الصبغ
05 Brake Condition		الفرامل
05.A Brake Pedal	SPONGY	دواسة الفرامل
06 Suspension System		ممتص الصدمات
06.A Ball Joint	BOOT CUT	مفصل كروي
07 Transmission Condition		الجير
07.A Road Test	NOT CHECK	فحص علي الطريق
07.B Visual Gear Box Condition	OIL LEAK ,JERKING	حالة الجير النظري
08 Steering Condition		المقود
08.A Steering Oil	OIL LEAK	زيت المقود
09 Chassis Condition		الشاصي
09.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
10 Engine Condition		المحرك
10.A Visual Engine Condition	MINOR OIL LEAK& INTAKE AIR PIPE DAMAGED,FIXED BY TAPE	حالة المحرك النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.



- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.