



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>28 Jul 2022, 13:15:51</b>
Transaction Number	<b>96733133 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>1FAHP2D84GG122250</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Ford</b>
Model	<b>Taurus</b>
Model Year	<b>2016</b>
Color	<b>Black</b>
Mileage	<b>127481 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>USA Imported</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A AC Condition	OK	المكيف
01.B Sun Visor	LEFT SIDE GLASS CRACKED	حاجب الشمس
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Fenders	REAR LEFT SIDE PORTION REPAIRED,REPAINTED & FRONT REFITTED	مذكار
02.B Bonnet	REFITTED	غطاء المحرك
02.C Paint	BODY PORTION REPAIRED,REPAINTED & MINOR DENT SCRATCHES	الصبغ
02.D Trunk	PORTION REPAIRED,REPAINTED	صندوق
02.E Floor	FLOOR DENT	الارضيه
<b>03 Tires and Rims Condition</b>		<b>الاطارات</b>
03.A Rims Condition	RIMS HAVE DENT SCRATCHES	حالة الجنوط
03.B Front Tyre	LEFT SIDE 2021 & RIGHT SIDE 2019 CRACKED	الاطار الامامي
03.C Rear Tyre	BOTH SIDE 2018 & CRACKED	الاطار الخلفي
<b>04 Chassis Condition</b>		<b>الشاصي</b>
04.A Chassis	FRONT LEFT SIDE CHASSIS END REPAIRED INNER MINOR	الشاصيه

DEFECT	REMARKS	
	RUSTY	
<b>05 Suspension System</b>		<b>ممتص الصدمات</b>
05.A Arms	LOWER ARM BUSHES CRACKED	ازرع
05.B Other	STABLIZER LINK BOOT CUT	اخري
05.C Ball Joint	BOOT CUT	مفصل كروي
<b>06 Steering Condition</b>		<b>المقود</b>
06.A Tie Rod End	BOOT CUT	مؤخرة الرودادت
<b>07 Transmission Condition</b>		<b>الجير</b>
07.A Road Test	NOT CHECK	فحص علي الطريق
07.B Visual Gear Box Condition	SIGN OF LEAK REFITTED	حالة الجير النظرى
07.C Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
<b>08 Seats Condition</b>		<b>المقاعد</b>
08.A Seat Condition	SEATS HAVE EXTRA COVER	حالة المقاعد
<b>09 Engine Condition</b>		<b>المحرك</b>
09.A Visual Engine Condition	MINOR OIL LEAK REFITTED	حالة المحرك النظرى
09.B Mount	MOUNT RUBBER CARCKED	كرسي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



X FAILED

Plate Details :	D 52126 Dubai Private
Chassis No :	1FAHP2D84GG122250
Vehicle Make :	FORD
Vehicle Model :	TAURUS
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Black
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	127482 Kms.
Origin : United States	Model Year : 2016
Gear Type : Automatic	Engine Size : 3500 CC
Engine No : NILL	Horse : 288
Axles No : 2	Power :
No Of : 4	Cylinders : 6
Doors :	No Of Seats : 5
G. V. W. : 2500 Kgs.	Empty : 1500 Kgs.
	Weight :

⚠ Retest can be done only in Dubai

Certificate Number :	5-TAS-2022-17373909		
Inspection Date :	09-08-2022		
Certificate Print Date :	09-08-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	15 min 42 sec		
Appointment Ref Number :	--		
Start Time :	13:55	End Time :	14:11
Lane :	01	Token No. :	163
Attempt :	1	Prints No. :	1

## Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
20 %	23 %	20 %	0.16 %
Vehicle on Petrol HC Reading			
3 PPM VOL			

## Inspection Findings

Defects	Issue	Severity
Tire change front right side tire side wall crack	Cracked	Major
Gear/Differential repair gear box oil leak	Others (Major)	Major
Vehicle Floor repair middle floor dent	Others (Major)	Major
Warning triangle not found	Missing	Major
Handbrake cable and bracket repair rear brake piper holder damage	Others (Major)	Major

## Inspection Remarks:

FRONT LEFT SIDE MEMBER , BULK HEAD , APRONS & RADIATOR FRAMES REPAIRED OK BY CHASSIS MEASUREMENT REPORT TRN : 2021-06-13-3 DATE 13 06 2021/minor body dent&scratches

## Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
3104	Cash	17373909	AED 170 Collected on 09/08/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Malek Tayseer Mustafa Othman

ⓘ This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

ⓘ Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أعراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

