



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	28 Sep 2022, 11:11:35
Transaction Number	50147338 (CC10006)	Queue Number	597326



Chassis Number	1HGCR2644HA610757
Engine Number	
Vehicle Class	Car
Manufacturer	Honda
Model	Accord
Model Year	2017
Color	Silver
Mileage	44323 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Tires and Rims Condition		الاطارات
01.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
02 Body		جسم المركبة
02.A Paint	BODY DENT,SCRATCHES	الصبغ
02.B Fenders	REAR LEFT SIDE DENT	مدكار
02.C Floor	UNDER FLOOR PORTION DENT.	الارضية
03 Transmission Condition		الجير
03.A Visual Gear Box Condition	OK	حالة الجير النظرى
03.B Road Test	NOT CHECKED.	فحص علي الطريق
04 Engine Condition		المحرك
04.A Visual Engine Condition	OK	حالة المحرك النظرى
05 Chassis Condition		الشاصي
05.A Chassis	CHECKED VISIBLE AREA OK.	الشاسيه
06 Interior Condition		الحاله الداخليه

DEFECT

REMARKS

06.A AC Condition

OK

المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.