CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934054
Transaction Date	03 Nov 2026, 17:00:07
Site Name	840 - Emirates Auctions
Transaction Number	74111243 (CC10026) (CC10026)



Vehicle Details

Chassis Number	WDD2193561*******
Specification	Imported
Make	Mercedes
Model	CLS 350
Model Year	2006
Color	Black
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT RIGHT SIDE & REAR LEFT SIDE REPAINTED PORTION REPAIRED , FRONT RIGHT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES	الصبغ
01.C Doors	REAR LEFT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY SIGN OF FLOODED	صدأ
01.E Floor	UNDER FLOOR , ENGINE , GEAR COVERED CHECK VISIBLE AREA ONLY	الارضية
01.F Bumper	MISALIGN , PORTION DAMAGE	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED , MISALIGN	غطاء المحرك
01.H Sign of front accident	FRONT BUMPER FRAME, BULKHEAD, RADIATOR SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FULLY COVERED , CHECK VISIBLE AREA ONLY	الشاسيه
02.B Other	NEED TO REMOVE INNER FENDER COVER & ENGINE UNDER COVER FOR PROPER INSPECTION	اخري
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION CRACK	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED MINOR OIL LEAK PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRACK & WORN OUT	الاطار الخلفي
06.C Rims Condition	DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED , LEFT SIDE BRACKET DAMAGE	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	GETTING RUSTY	دسك وطنابير الفرامل
09 Interior Condition		الحاله الداخليه
09.A Other	CENTER CONSOLE PANEL DAMAGE	اخري
09.B AC Condition	NOT CHECK	المكيف
09.C Dash Board	GLOVE BOX PORTION WORN OUT	لوحة القياده
09.D Roof Ceiling	PORTION WORN OUT	بطانه السقف
09.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.F Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
09.G Gear Shifting Lever	KNOB PORTION WORN OUT , PANEL PORTION DAMAGE	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae